

Spill Prevention Control & Countermeasures Plan (SPCC)

SPCC Prepared For:

Coastal Energy Corporation 1 Coastal Drive Willow Springs, MO 65793

SPCC Prepared By:

Environmental Works, Inc. 1455 E. Chestnut Expy Springfield, MO 65802 417-890-9500

SPCC Prepared:

June 2014 Project # 140201

Table of Contents

Table of Contents	
List of Figures & Tables	
List of Appendices	. iv
Purpose	v
1.0 Plan Administration	1
1.1 Management Approval and Designated Person (40 CFR 112.7)	
1.2 Professional Engineer Certification (40 CFR 112.3(d))	1
1.3 Location of SPCC Plan (40 CFR 112.3(e))	2
1.4 Plan Review (40 CFR 112.3 and 112.5)	3
1.4.1 Changes in Facility Configuration	3
1.4.2 Scheduled Plan Reviews	
1.4.3 Record of Plan Reviews	4
1.5 Facilities, Procedures, Methods, or Equipment Not Yet Fully Operational (40 CFR 112.7	7)4
1.6 Cross-Reference with SPCC Provisions (40 CFR 112.7)	5
2.0 General Facility Information (40 CFR 112.7)	6
2.1 Facility Description (40 CFR 112.7 (a)(3))	6
2.1.1 Location and Activities	6
2.1.2 Oil Storage (40CFR 112.7(a)(3)(i))	
2.2 Evaluation of Discharge Potential	7
2.2.1 Distance to Navigable Waters and Adjoining Shorelines and Flow Paths	7
2.2.2 Discharge History	7
3.0 Discharge Prevention—General SPCC Provisions	8
3.1 Compliance with Applicable Requirements (40 CFR 112.7 (a)(2))	
3.2 Facility Layout Diagram (40 CFR 112.7 (a)(3))	8
3.3 Spill Reporting (40 CFR 112.7 (a)(4))	8
3.4 Potential Discharge Volumes and Direction of Flow (40 CFR 112.7 (b))	8
3.5 Containment and Diversionary Structures (40 CFR 112.7 (c))	9
3.6 Practicability of Secondary Containment (40 CFR 112.7 (d))	9
3.7 Inspections, Tests, and Records (40 CFR 112.7 (e))	9
3.7.1 Daily Inspection	
3.7.2 Monthly Inspection	
3.7.3 Annual Inspection	
3.7.4 Periodic Integrity Testing	. 12
3.8 Personnel, Training, and Discharge Prevention Procedures (40 CFR 112.7(f))	. 12



3.9 Security (40 CFR 112.7 (g))
3.10 Tank Truck Loading/Unloading Rack Requirements (40 CFR 112.7 (h))13
3.10.1 Secondary Containment (40 CFR 112.7 (h)(1))
3.10.2 Loading/Unloading Procedures (40 CFR 120.7 (h)(2) and (3))14
3.11 Brittle Fracture Evaluation (40 CFR 112.7 (i))
3.12 Conformance with State and Local Applicable Requirements (40 CFR 112.7 (j)) 14
3.13 Qualified Oil-filled Operational Equipment (40 CFR 112.7 (k))
4.0 Discharge Prevention; Provisions for Onshore Facilities (Excluding Production Facilities)16
4.1 Facility Drainage (40 CFR 112.8(b))
4.2 Bulk Storage Containers (40 CFR 112.8(c))
4.2.1 Construction (40 CFR 112.8 (c)(1))
4.2.2 Secondary Containment (40 CFR 112.8(c)(2))
4.2.3 Drainage of Containment Structures (40 CFR 112.8(c)(3))
4.2.4 Corrosion Protection (40 CFR 112.8(c)(4))
4.2.5 Partially Buried and Bunkered Storage Tanks (40 CFR 112.8(c)(5))17
4.2.6 Inspections and Tests (40 CFR 112.8(c)(6))
4.2.7 Heating Coils (40 CFR 112.8(c)(7))
4.2.8 Overfill Prevention Systems (40 CFR 112.8(c)(8))
4.2.9 Effluent Treatment Facilities (40 CFR 112.8(c)(9))
4.2.10 Visible Discharges (40 CFR 112.8(c)(10))19
4.2.11 Mobile and Portable Containers (40 CFR 112.8(c)(11))
4.3 Transfer Operations, Pumping, and In-Plant Processes (40 CFR 112.8(d))20
5.0 Discharge Response
5.1 Response to Minor Discharge
5.2 Response to Major Discharge
5.3 Waste Disposal
5.4 Discharge Notification
5.5 Cleanup Contractors and Equipment Suppliers25



Coastal Energy Corporation

List of Figures & Tables

	Page
Table 1.1–Record of Plan Reviews and/or Evaluation Certification	4
Table 1.2–SPCC Cross-Reference	5
Table 2.1–Oil Containers and Possible Discharges	Appendix L
Table 2.2–Oil Discharge History	7
Table 3.1-Inspection and Testing Program	10
Figure 1.0-Facility Location Map	Appendix A
Figure 2.0–Facility Site Map	Appendix A
Figure 3.0–Facility Site Map	Appendix A
Figure 4.0–Facility Site Map	Appendix A



List of Appendices

Appendix A - Site Map and Facility Diagram

Appendix B - Substantial Harm Determination

Appendix C – Facility Inspection Checklists

Appendix D – Record of Secondary Containment Drainage

Appendix E – Record of Discharge Prevention Briefings and Training

Appendix F - Calculation of Secondary Containment Capacity

Appendix G –Records of Tank Integrity and Pressure Tests

Appendix H-Emergency Contacts

Appendix I – Discharge Notification Form

Appendix J-Discharge Response Equipment Inventory

Appendix K-Agency Notification Standard Report

Appendix L-Table 2.1 Oil Containers and Potential Discharge

Appendix M-Notice to Tank Vehicle Drivers



Purpose

The purpose of this Spill Prevention, Control, and Countermeasure (SPCC) Plan is to describe measures implemented by the Coastal Energy Corporation (Coastal Energy) facility to prevent oil discharges from occurring and to be prepared to respond in a safe, effective, and timely manner to mitigate the impacts of a discharge.

This SPCC Plan has been prepared in accordance with Title 40 Code of Federal Regulations Part 112 (40 CFR Part 112), and subsequent amendments. This SPCC Plan is used as a reference for oil storage information, as a tool to communicate practices on preventing and responding to discharges with employees, as a guide to facility inspections, and as a resource during emergency response.

In accordance with 40 CFR 112 any facility which could "reasonably be expected to discharge oil in quantities that may be harmful into or upon the navigable waters of the United States or adjoining shorelines" is required to prepare and implement a plan to prevent any discharge of oil in quantities that violate applicable water quality standards, cause a sheen upon or discoloration of the surface of navigable waters or adjoining shorelines, or cause a sludge or emulsion to be deposited beneath the surface of the water or upon adjoining shorelines. The plan is known as the facility's Spill Prevention Control and Countermeasure (SPCC) Plan. Any owner or operator of a non-transportation related onshore or offshore facility engaged in drilling, producing, gathering, storing, processing, refining, transferring, distributing, using, or consuming oil and oil products is required to have an SPCC Plan. Facilities subject to this rule are further defined as those with an aggregate capacity of more than 1,320 gallons of aboveground storage (stored in containers ≥ 55-gallons) or more than 42,000 gallons of underground storage and which, due to their location, could reasonably be expected to discharge oil in harmful quantities into or upon the navigable waters of the United States or adjoining shorelines.

Since the Coastal Energy facility has petroleum storage with a total capacity greater than 1,320-gallons, it is subject to the SPCC Plan rule. All oil storage containers of petroleum-based oils and lubricants greater than or equal to 55-gallons must be included in the SPCC Plan.

According to the Clean Water Act (CWA), as amended by the Oil Pollution Act (OPA), certain facilities that store and use oil are required to prepare and submit plans to respond to a worst case discharge of oil and to a substantial threat of such a discharge. EPA has established regulations that define who must prepare and submit a Facility Response Plan (FRP) and what must be included in the plan. An FRP is a plan for responding, to the maximum extent practicable, to a worse case discharge, and to a substantial threat of such a discharge, of oil. The Plan also includes responding to small and medium discharges as appropriate.

According to OPA, an owner or operator of a "substantial harm" facility must develop and implement an FRP. A "substantial harm" facility is a facility that, because of its location, could reasonably be expected to cause substantial harm to the environment by discharging oil into or on navigable waters or adjoining shorelines. EPA's Facility Response Plan requirements were published as a final rule in the Federal Register on July 1, 1994, and codified at 40 CFR 112.20 and 112.21, including Appendices B through F.

The FRP helps an owner or operator develop a response organization and ensure the availability of response resources (i.e., response equipment, trained personnel) needed to respond to an oil discharge. The FRP also demonstrates that the response resources are available in a timely manner, thereby reducing a discharge's impact and severity. The FRP also helps a facility owner or operator improve



discharge prevention measures through the early identification of risks at the facility. In addition, FRPs aid local and regional response authorities to better understand the potential hazards and response capabilities in their area.

The Coastal Energy facility does meet the determination requirements for a substantial harm to the environment based on the completion of The Substantial Harm Determination in **Appendix B** from 40 CFR Part 112.

The Coastal Energy facility has greater than 1 million gallons of aggregate petroleum storage with secondary containment sufficiently large enough to contain the capacity of the largest aboveground oil storage tank within each storage area plus sufficient freeboard to allow for precipitation. Although sufficient secondary containment exists at the site, the Regional Administrator (RA) has determined that the facility is located at a distance such that a discharge from the facility could cause injury to fish and wildlife and sensitive environments.

The Coastal Energy facility has prepared a Facility Response Plan (FRP) in accordance with the requirements of 40 CFR 112.20 and 112.21, including Appendices B through F. This Plan provides guidance on key actions that Coastal Energy facility personnel must perform to comply with the SPCC Plan rule:

- Complete monthly and annual site inspections as outlined in the Inspection, Tests, and Records section of this plan (Sections 3.7 & 4.2.6) using the inspection checklist included in Appendix C.
- Perform preventive maintenance of equipment, secondary containment systems, and discharge prevention systems described in this Plan as needed to keep them in proper operating conditions.
- Conduct annual employee training as outlined in the Personnel, Training, and Spill Discharge
 Procedures section of this Plan (Section 3.8) and document them on the logs included in
 Appendix E.
- If either of the following incidents occurs, submit the SPCC Plan to the EPA Region VII RA and the Missouri Department of Natural Resources (MDNR), along with other information as detailed in Section 5.4 of this Plan.
 - The facility discharges more than 1,000 gallons of oil into or upon the navigable waters of the U.S. or adjoining shorelines in a single spill event, or;
 - The facility discharges oil in quantity greater than 42 gallons in each of two spill events within any 12-month period.
- Review the SPCC Plan at least once every five years and amend it to include more effective
 prevention and control technologies, if such technologies will significantly reduce the likelihood
 of a spill event and has been proven effective in the field at the time of the review. Plan
 amendments, other than administrative changes, must be recertified by a professional Engineer
 on the certification page in Section 1.2 of this Plan.
- Amend the SPCC Plan within six months whenever there is a change in the facility design, construction, operation, or maintenance that materially affects the facility's spill potential. The revised Plan must be recertified by a Professional Engineer (PE).
- Review the Plan on an annual basis. Update the Plan to reflect any administrative changes that
 are applicable, such as personnel changes or revisions to contact information, such as phone
 numbers. Administrative changes must be documented as per the Plan review log of Section 1.4
 of this Plan, but do not have to be certified by a P.E.



1.0 Plan Administration

1.1 Management Approval and Designated Person (40 CFR 112.7)

The facility is committed to preventing discharges of oil to navigable waters and the environment, and to maintaining the highest standards for spill prevention control and countermeasures through the implementation and regular review and amendment to the plan. This SPCC has the full approval of management. The facility has committed the necessary resources to implement the measures described in this plan.

Authorized Facility Representative:	
Signature:	
A security of the state of the strike of the state of the	
Name:	
Title:	
Date:	

1.2 Professional Engineer Certification (40 CFR 112.3(d))

The undersigned Registered Professional Engineer is familiar with the requirements of Part 112 of Title 40 of the *Code of Federal Regulations* (40 CFR part 112) and has visited and examined the facility, or has supervised examination of the facility by appropriately qualified personnel. The undersigned Registered Professional Engineer attests that this Spill Prevention, Control, and Countermeasure Plan has been prepared in accordance with good engineering practice, including consideration of applicable industry standards and the requirements of 40 CFR part 112; that procedures for required inspections and testing have been established; and that this Plan is adequate for the facility. [40 CFR 112.3(d)]

This certification in no way relieves the owner or operator of the facility of his/her duty to prepare and fully implement this SPCC Plan in accordance with the requirements of 40 CFR part 112. This Plan is valid only to the extent that the facility owner or operator maintains, tests, and inspects equipment, containment, and other devices as prescribed in this Plan.



ENGINEER CERTIFICATION

Name	of	Faci	lity:
------	----	------	-------

Coastal Energy Corporation

Type of Facility:

Bulk Oil Plant

Location of Facility:

1 Coastal Drive

Willow Springs, MO 65793

Name and Address

Coastal Energy Corporation

Of Operator:

1 Coastal Drive Willow Springs, MO 65793

Designated Person Responsible:

Gary Picard, SPCC Plan Coordinator

Management Approval

Full approval is extended by management at a level with authority to commit the necessary resources for implementation of the SPCC Plan.

Signature	Date	Fit Washington and St.
Name	Title	di dalam per

Certification

I hereby certify that this facility has either been examined by me or by individuals under my supervision, and being familiar with the provisions of 40 CFR, Part 112, I attest that this SPCC Plan has been prepared in accordance with good engineering practices (including consideration of applicable industry standards and with requirements of Part 112), and the SPCC Plan is adequate for this facility. Furthermore, I certify that procedures for required inspections and testing have been established.

Name and PE Registration Number:

Duane Ottmar, E-24241

Title:

Professional Engineer

Date:

August 8, 2014

Engineer's Seal and Signature:





1.3 Location of SPCC Plan (40 CFR 112.3(e))

In accordance with 40 CFR 112.3(e), a complete copy of this SPCC shall be maintained at the Coastal Energy facility. A copy shall be available to the U.S. Environmental Protection Agency (EPA) Regional Administrator, Missouri Department of Natural Resources, or designated agent, for on-site review during normal working hours.

1.4 Plan Review (40 CFR 112.3 and 112.5)

1.4.1 Changes in Facility Configuration

In accordance with 40 CFR 112.5(a), Coastal Energy personnel shall periodically review and evaluate this SPCC Plan for any change in the facility design, construction, operation, or maintenance that materially affects the facility's potential for an oil discharge, including, but not limited to:

- Addition of new oil storage containers.
- Reconstruction, replacement, or installation of piping systems.
- Construction or demolition that might alter secondary containment structures;
- Changes of product or service, revisions to standard operations, modification of testing/inspection procedures, and use of new or modified industry standards or maintenance procedures.

Amendments to this Plan made to address changes of this nature are referred to as technical amendments, and must be certified by a Professional Engineer (P.E). Non-technical amendments can be done (and must be documented) by the facility owner and/or operator. Non-technical amendments include the following:

- Change in the name of contact information such as telephone numbers of individuals responsible for the implementation of this Plan or outside contractors and agencies.
- Change in the name or contact information of spill response or cleanup contactors.

The Coastal Energy management shall make the needed revisions to the SPCC Plan as soon as possible, but no later than six months after the change occurs. The Plan must be implemented as soon as possible following the technical amendment, but no later than six months from the date of the amendment. The SPCC Plan Coordinator is responsible for initiating and coordinating revisions to the SPCC Plan.

1.4.2 Scheduled Plan Reviews

In accordance to 40 CFR 112.5(b), the Coastal Energy SPCC Plan Coordinator shall review the SPCC Plan at least once every five years. Revisions to the SPCC Plan shall be made within six months of the five-year review. If the review indicates that changes to the SPCC Plan are necessary, Coastal Energy facility personnel shall arrange to make the necessary changes and shall obtain recertification by a registered Professional Engineer (P.E). The registered P.E. shall certify any technical amendments to the SPCC Plan, as described above, in accordance with 40 CFR 112.5(c).

This SPCC Plan is dated June 2014. The next plan review is scheduled on or prior to June 2019, unless there are technical changes to oil storage containers and systems.



1.4.3 Record of Plan Reviews

Scheduled reviews and Plan amendments are recorded in the Plan Review Log (Table 1-1). This log must be completed even if no amendment is made to the Plan as a result of the review. Unless a technical or administrative change prompts an earlier review of the Plan, the next scheduled review of this Plan must occur by June 23, 2019.

Table 1.1 Record of Plan Reviews and/or Evaluation Certification

Name	Date	Activity	PE Certification Required	Comments
				ST HOUSE, of
			Correspondent States	Manager Street
				Mary - Carlons
				manual array
		The Paris	· LEVENT	4. 1:31 (1:31 (1:3)
				Constitution Co. 1
				Alaka s
		-	The first state of	H - NTAY
		ette o rocci e e	er in	Provide Charles
				LA SACIO CATA
		Line to a	than the	No. 4 State of the Paris
				Krong mad to Mynas
		Marie Carles Mar	Trader-re-	

1.5 Facilities, Procedures, Methods, or Equipment Not Yet Fully Operational (40 CFR 112.7)

The facility does not have any procedures, methods, or equipment not yet fully functional.



1.6 Cross-Reference with SPCC Provisions (40 CFR 112.7)

This SPCC Plan does not follow the exact order presented in 40 CFR part 112. **Table 1.2** presents a cross-reference of Plan sections relative to applicable parts of 40 CFR part 112.

Table 1.2 SPCC Cross-Reference

Provision	Plan Section	Page
112.3(d)	Professional Engineer Certification	1
112.3(e)	Location of SPCC Plan	2
112.5	Plan Review	2
112.7	Management Approval	1
112.7	Cross-Reference with SPCC Rule	- 5
112.7(a)(3)	General Facility Information Appendix A: Site Plan and Facility Diagram	6
112.7(a)(4)	Discharge Notification	24
112.7(a)(5)	Discharge Response	22
112.7(b)	Potential Discharge Volumes and Direction of Flow	8
112.7(c)	3.5 Containment and Diversionary Structures	9
112.7(d)	3.6 Practicability of Secondary Containment	9
112.7(e)	3.7 Inspections, Tests, and Records	9
112.7(f)	3.8 Personnel, Training and Discharge Prevention Procedures	12
112.7(g)	3.9 Security	12
112.7(h)	3.10 Tank Truck Loading/Unloading	13
112.7(i)	3.11 Brittle Fracture Evaluation	14
112.7(j)	3.12 Conformance with Applicable State and Local Requirements	14
112.7(k)	3.13 Qualified Oil-filled Operational Equipment	15
112.8(b)	4.1 Facility Drainage	16
112.8(c)(1)	4.2.1 Construction	16
112.8(c)(2)	4.2.2 Secondary Containment	16
112.8(c)(3)	4.2.3 Drainage of Diked Areas	16
112.8(c)(4)	4.2.4 Corrosion Protection	16
112.8(c)(5)	4.2.5 Partially Buried and Bunkered Storage Tanks	17
112.8(c)(6)	4.2.6 Inspection Appendix C - Facility Inspection Checklists	17
112.8(c)(7)	4.2.7 Heating Coils	19
112.8(c)(8)	2.8(c)(8) 4.2.8 Overfill Prevention System	
112.8(c)(9)	4.2.9 Effluent Treatment Facilities	19
112.8(c)(10)	4.2.10 Visible Discharges	19
112.8(c)(11)	4.2.11 Mobile and Portable Containers	20
112.8(d)	4.3 Transfer Operations, Pumping and In-Plant Processes	20
112.20(e)	Certification of Substantial Harm Determination Appendix B	28



2.0 General Facility Information (40 CFR 112.7)

Name: Coastal Energy Corporation

Address: 1 Coastal Drive

Willow Springs, MO 65793

Type: Manufacturer of Asphalt Oils

Owner/Operator: Coastal-FMC

1 Coastal Drive

Willow Spring, MO 65793

Primary contact: Gary Picard, SPCC Coordinator

417-469-2777 (O) 417-855-0194 (C)

2.1 Facility Description (40 CFR 112.7 (a)(3))

2.1.1 Location and Activities

The Coastal Energy complex, although contiguous, is divided into two sections; the Bulk Plant and the Maintenance Facility. The Coastal Energy Bulk Plant is located at 232 Burnham Road Willow Springs, Missouri 65739 and the Maintenance Shop portion of the facility is located at 1 Coastal Drive Willow Springs, Missouri 65793. The Coastal Energy facility occupies a portion of the Eastern ½ of Section 32, Township 27 North, Range 9 West in Howell County, Missouri. The site location of the facility is depicted in Figure 1, a portion of the United States Geologic Survey Willow Springs South, Missouri Quadrangle Map. Figure 1 is included in Appendix A. The facility is located south of U.S Hwy 60/63 in Willow Springs, Missouri. The land surrounding the property includes undeveloped land and industrial properties.

The Coastal Energy facility is staffed Monday through Friday from 8 AM through 5 PM. Personnel are on site continuously during operating periods.

Rain water from the Bulk Plant area of the property is generally retained on site due to the earthen berm that surrounds the entire area. The capacity for this area is 2,812,000 gallons. Rainwater collected in this area is pumped to the central portion of the Bulk Plant where infiltration and evaporation occurs. Rain water from the Maintenance Shop portion of the facility drains west to the Eleven Point River. Sanitary wastewater generated at the Coastal Energy facility is discharged to the City of Willow Springs sanitary wastewater system.

The Site Map and Facility Diagram included in **Appendix A** of this Plan show the general site location and layout of the facility. The Facility Diagram (**Figure 2**) shows the location of oil containers, buildings, loading/unloading and transfer areas, and critical spill control structures.

2.1.2 Oil Storage (40CFR 112.7(a)(3)(i))

Figures 2, 3, and 4 (Appendix A) are facility layout diagrams for the Coastal Energy facility that illustrates the layout of oil storage areas. Information for each container, including the type of petroleum product storage capacity, and type of secondary containment is summarized in Table 2-1 (Appendix L).



In the December 6, 2006 Federal Register amendments to the 40 CFR 112 SPCC Plan rules, EPA included an exemption for "motive power containers" from having to be covered by a SPCC Plan. A motive power container is defined as "any onboard bulk storage container used primarily to power the movement of a motor vehicle, or ancillary onboard oil-filled operational equipment". Therefore, the petroleum tanks and hydraulic oil tanks on the vehicles at the facility do not have to be included in this SPCC Plan.

2.2 Evaluation of Discharge Potential

2.2.1 Distance to Navigable Waters and Adjoining Shorelines and Flow Paths

According to 40 CFR 112.7(b), where experience indicates a reasonable potential for equipment failure (tank overflow, tank rupture, and leakage, loading or unloading) the SPCC Plan should include a prediction of the direction, rate of flow, and the total amount of petroleum that could be discharged from the facility as a result of each type of equipment failure. For each oil storage container, Table 2-1 (Appendix L) lists the direction, rate of flow, and the total amount of petroleum that could be discharged from the facility. The surface drainage direction of the Bulk Plant portion of the facility is to the east towards the Eleven Point River. The surface drainage direction of the Maintenance Shop portion of the facility is to the east towards the Eleven Point River.

2.2.2 Discharge History

There has not been a reportable discharge as described in 40 CFR 112.1(b) from the Coastal Energy facility since it began operations. Table 2.2 summarizes the facility's discharge history.

Table 2.2 Discharge History

Description of Discharge	Corrective Actions Taken	Plans for Preventing Recurrence	
	×		
	Ministration of the same	and either a droit street	
	0.100	to the decrease and and from the second	
		The second of the second of the second	
	(1-14		
	er mediciti x = titlen yang	Marie and Marie Control of the control of	
	profile not sell of an information		
No said of thing of the	and Service And Antonography School	Commontation of the second	



3.0 Discharge Prevention—General SPCC Provisions

The following measures are implemented to prevent oil discharges during the handling, use, or transfer of oil products at the facility. Oil-handling employees have received training in the proper implementation of these measures.

3.1 Compliance with Applicable Requirements (40 CFR 112.7 (a)(2))

All petroleum storage tanks and containers at the Coastal Energy facility are provided with either sized secondary containment, an earthen berm secondary containment system (retention pond), double-walled tank systems, or general secondary containment. All bulk oil storage tanks are provided with sized secondary containment structures, including; concrete and/or earthen berm containment. The oil filled equipment, 55-gallon steel drums, 5-gallon buckets, and smaller oil containers are either stored in sized secondary containment or meet general secondary requirements. Information for each container, including the type of petroleum product stored, storage capacity, and type of secondary containment is summarized in Table 2-1 (Appendix L).

All bulk oil storage tanks are provided with secondary containment structures consisting of concrete floors and walls or retention areas that meet requirements of 40 CFR 112.7(c) for general secondary containment and 40 CFR 112.8(c) for sized secondary containment. Petroleum storage drums are stored throughout the facility and potential spills are contained within general secondary containment. In addition, the facility has a mobile response trailer with appropriate spill response materials to aide in spill response procedures as outlined in the Facility's Response Plan. Figures 1 and 2 (Appendix A) illustrates the location of the Coastal Energy facility and the oil containers and spill absorbent material. For any oil spills, appropriate response actions are described in Section 5.0.

Recommended Practices

- Containers will be stored in a manner and area to minimize or prevent damage or rupture of containers.
- Portable containers (drums) will be closed while not in use.
- Care will be taken while removing contents for use.
- Outside of containers will be observed by personnel for signs of deterioration or leakage.
- Corrective measure will be made for all discrepancies observed.

3.2 Facility Layout Diagram (40 CFR 112.7 (a)(3))

Figures 1 and 2 in Appendix A illustrate the facility layout, which includes the locations of above ground oil storage containers, transfer stations, and connecting pipes. As required under 40 CFR 112.7(a)(3), the facility diagram indicates the location and content of ASTs, USTs, transfer stations, and connecting piping.

3.3 Spill Reporting (40 CFR 112.7 (a)(4))

The discharge notification form included in **Appendix I** will be completed upon immediate detection of a discharge and prior to reporting a spill to the proper notification contacts.

3.4 Potential Discharge Volumes and Direction of Flow (40 CFR 112.7 (b))

Table 2.1 located in Appendix L presents expected volume, discharge rate, general direction of flow in the event of equipment failure, and means of secondary containment for different parts of the facility where oil is stored, used, or handled.



3.5 Containment and Diversionary Structures (40 CFR 112.7 (c))

This section presents information required by 40 CFR 112.7(c), which lists the requirement that appropriate secondary containment structures or equipment be provided to prevent a discharge; by 40 CFR 112.7(a)(3)(iii), which requires a discussion of the secondary containment methods for oil storage and other procedures for control of discharges; and by 40 CFR 112.7(d), which requires an explanation where secondary containment is not practical for bulk storage containers.

The general requirements in 40 CFR 112.7(c) include providing appropriate containment, diversionary structures, or equipment to prevent an oil discharge. The following methods are listed as appropriate containment methods in 40 CFR 112.7(c).

- Dikes, berms, or retaining walls sufficiently impervious to contain oil;
- Curbing;
- Culverting, gutters, or other drainage systems;
- Weirs, booms, or other barriers;
- Spill diversion ponds;
- Retention ponds;
- Sorbent materials.

The containment system must be capable of containing an oil spill until cleanup occurs. If the installation of one of any of the above structures or pieces of equipment is not practicable, this SPCC Plan shall explain why the installation is not practicable, provide measures for periodic integrity testing of containers, periodic integrity and leak testing of valves and piping on bulk storage, includes an oil spill contingency plan, and includes a written commitment of manpower, equipment, and materials to quickly control and remove any harmful discharges as required by 40 CFR 112.7 (d).

Secondary containment is the main discharge prevention and control measure used at the Coastal Energy facility. Secondary containment is provided for all oil containers. In addition, there are spill kits located in the product offloading and loading areas at the Bulk Plant, in the Maintenance Shop area, and near the fueling tanks in the Maintenance Shop area; where spills are most likely to occur. Additionally, the facility has a spill response trailer that can be mobilized immediately anywhere within the facility. Information for each container, including the type of petroleum product stored, storage capacity, and type of secondary containment is summarized in Table 2-1 (Appendix L).

3.6 Practicability of Secondary Containment (40 CFR 112.7 (d))

All of the aboveground storage Tanks (ASTs) at this facility are listed in Table 2-1. All ASTs are either provided with secondary containment or general secondary containment as indicated in Table 2-1. Coastal Energy has determined that secondary containment is practical at this facility.

3.7 Inspections, Tests, and Records (40 CFR 112.7 (e))

As required by the SPCC rule, the facility performs the inspections, tests, and evaluations listed in Table 3-1, the table summarizes the various types of inspections and tests performed at the facility. Aboveground storage containers, associated piping, and secondary containment systems are to be inspected in accordance with the inspection procedures and forms provided in Appendix C. The Facility Manager is responsible for ensuring these inspections are performed as required and all items requiring corrective actions are addressed. Completed inspection forms are to be signed by the inspector and maintained with the official copy of this Plan for at least three years.



Table 3.1 Inspection and Testing Program

Facility Component	Action	rtion Following a regular schedule (monthly, annual, and during scheduled inspections) and whenever material repairs are made.	
Aboveground container	Test container integrity. Combine visual inspection with another testing technique (non-destructive shell testing). Inspect outside of container for signs of deterioration and discharges		
Container supports and foundation	Inspect container's supports and foundations	Following a regular schedule (monthly, annual, and during scheduled inspections) and whenever material repairs are ma	
Liquid level sensing devices Sight Gauges (overfill)	Test for proper operation.	Monthly	
All aboveground valves, piping, and appurtenances	Assess general condition of items, such as flange joints, expansion joints, valve glands and bodies, catch pans, pipeline supports, locking of valves, and metal surfaces.	Monthly	

3.7.1 Daily Inspection

An employee shall perform a complete walk-through of the facility each day. This daily visual inspection involves: (1) looking for tank/piping damage or leakage, stained or discolored soils, or excessive accumulation of water in secondary containment areas; (2) observing the facilities stormwater effluent and (3) verifying that the facility's BMPs are functioning and in proper working order. The daily visual inspection does not have a requirement for record keeping or retention.

3.7.2 Monthly Inspection

The checklist provided in **Appendix C** is used for monthly inspections. The monthly inspections cover the following key elements:

- Observing the exterior of aboveground storage tanks, pipes, and other equipment for signs of deterioration, leaks, corrosion, and thinning.
- Observing the exterior of portable containers for signs of deterioration or leaks.
- Observing tank foundations and supports for signs of instability or excessive settlement.
- Observing the tank fill and discharge pipes for signs of poor connection that could cause a discharge, and tank vent for obstructions and proper operation.
- Verifying the proper functioning of overfill prevention systems.
- Checking the inventory of discharge response equipment and restocking as needed.
- Observing the effluent and measuring the quantity of accumulated oil within the oil/water separator.



Visible piping, valves, and pumps will be visually inspected monthly for signs of leakage. The outside of the piping, valves, pumps, seams, gaskets, rivets, and bolts will be visually inspected for evidence of deterioration or leaks that might cause a spill or accumulation of oil inside the containment. All above ground piping, valves, and pumps will be periodically inspected by facility personnel for the condition of such things as flange joints, expansion joints, valve glands and bodies, catch pans, pipe supports, valve locks, and metal surface conditions. Prompt corrections will be made to any item that is discharging oil and any accumulation of oil in diked areas will be promptly and properly removed as required in 40 CFR 112.8 (c) (10). Periodic integrity and leak testing of the valves and piping will be conducted. Inspection records will be kept on the inspections, tests, and repairs made. All problems regarding tanks, piping, containment, or response equipment must immediately be reported to the Facility Manager. Visible oil leaks from tank walls, piping, or other components must be repaired as soon as possible to prevent a larger spill or a discharge to navigable waters or adjoining shorelines. Pooled oil is removed immediately upon discovery.

As required in 40 CFR 112.8 (d), buried piping that was installed or replaced on or after August 16, 2002 must have a protective wrapping and coating. All underground piping must satisfy the corrosion protection standards for piping in part 40 CFR 280 and any state program under 40 CFR 281. Any corrosion damage visible from the surface must undergo corrective action based on the magnitude of the damage. When a pipe is not in service for an extended period of time, the terminal connection must be capped or blank-flanged at the transfer point and marked as to its origin. Pipe support design included an allowance for expansion and contraction to minimize abrasion and corrosion.

The only underground piping associated with the Coastal Energy facility is located between the ethanol rail unloading area and the ethanol bulk storage tanks. The piping transfers the ethanol product from rail cars into the bulk storage area a distance of approximately 45-feet. The pipe is buried approximately 5-feet underground. The piping consists of steel pipe and has a double walled protection system that overfills and alerts operators if the underground piping system has failed. The testing system consists of a ball valve regulator that is opened before and after each transfer to check for fugitive product. If fugitive product is not visible, the transfer from the rail car to the bulk storage tanks is initiated.

Although this section of pipe does not have cathodic protection it does meet the regulatory requirements of 40 CFR 280.40(a)(1) and (2). The system provides a method of release detection that can detect a release from any portion of the underground piping that routinely contains product. 40 CFR 280.44(c) indicates that any of the methods in 40 CFR 280.43 (e) through (f) may be used if they are designed to detect a release from any portion of the underground piping that routinely contains regulated substances. In accordance with 40 CFR 280.43(g), the system utilizes interstitial monitoring which is designed, constructed and installed to detect a leak from any portion of the [piping] that routinely contains product. Additionally, the double walled monitoring system used for this portion of underground piping, in accordance with 40 CFR 280.43(g)(1), is a double-walled [piping] system whereas the test method outlined can detect a release from the inner wall in a portion of the [piping] that routinely contains product.

Written monthly inspection records shall be signed by the Facility Manager and maintained with this SPCC Plan for a period of three years.

The condition of secondary containment structures will be inspected at the same time that the containers and piping are inspected. Records will be kept on the inspections, combined with other



records, and kept with the SPCC Plan. Inspection Checklist forms are included in **Appendix C** and can be used to record these activities.

The condition and quantity of spill control equipment will also be inspected at the same time that the containers and piping are inspected. Records will be kept of the inspections and kept with the SPCC Plan. Inspection Checklist forms included in **Appendix C** can be used to record these activities.

3.7.3 Annual Inspection

Facility personnel shall perform a more thorough inspection of facility equipment on an annual basis. This annual inspection complements the monthly inspection described above and is performed each year using the checklist provided in **Appendix C** of this Plan.

The annual inspection is preferably performed after a large storm event in order to verify the imperviousness and/or proper functioning of drainage control systems such as; secondary containment structures, dikes, rollover berms, control valves and oil/water separators.

Written annual inspection records are signed by the Facility Manager and maintained with this SPCC Plan for a period of three years.

3.7.4 Periodic Integrity Testing

In addition to the above monthly and annual inspections by facility personnel, the ASTs are to be subjected to periodic integrity testing using techniques such as hydrostatic testing, visual inspection or non-destructive shell thickness tests. Corrective measures shall be made for all discrepancies observed. Specific AST inspection forms are stored in **Appendix G**.

Tanks shall be periodically evaluated by an outside certified tank inspector following the American Petroleum Institute (API) 653 or the Steel Tank Institute (STI) Standard for the Inspection of Aboveground Storage Tanks, SP-001, as described in Section 4.2.6 of this Plan.

3.8 Personnel, Training, and Discharge Prevention Procedures (40 CFR 112.7(f))

For this facility, the SPCC Coordinator is responsible for providing the proper spill prevention instruction to all personnel involved in fuel/oil handling and/or equipment maintenance.

Training for personnel is to be conducted at least annually to assure adequate understanding of this facility plan. This training is to highlight all applicable pollution control laws, rules and regulations, discharge clean-up procedures, and Best Management Practices (BMPs) to prevent discharges of oil. The training is to also include descriptions of any known discharge events or failures, malfunctioning components, and recently developed precautionary measures. The Personnel Training form included in Appendix E should be completed to document personnel training and practice drills. Completed documentation should be kept with this plan for three years.

3.9 Security (40 CFR 112.7 (g))

The SPCC Plan regulations requires that a facility describe in your plan how you secure and control access to the oil handling, processing, and storage areas; secure master flow and drain valves; prevent unauthorized access to starter controls on oil pumps; secure out-of-service and loading/unloading connection of oil pipelines; and address the appropriateness of security lighting to both prevent acts of vandalism ans assist in the discovery of oil discharges.



The northern portion of the Coastal Energy facility is protected by a gated fence with while other access points to the facility are controlled by identification card access and security. Buildings and the general exterior of the facility at the Coastal Energy facility are well lit to help deter acts of vandalism and aid personnel in detecting spills.

The Coastal Energy facility is equipped with the following safety measures and deterrents that can prevent a spill:

- A partial fence along Eleven Point River, from front gate to the highway
- 24 hour lighting
- 24 hour video surveillance
- 24 hour alarm on main buildings

When in non-operating or non-standby service, valves that permit direct outward flow from an oil storage container to the surface are to be kept securely locked in a closed position. This can be accomplished by incorporating any of the following methods:

Additional safety practices should include:

- · Adding locks directly to padlock wings of the valve,
- Adding locks to hasps, chains, or comparable hardware to the valve operating stem (or operating handle),
- Closing adjacent valves and adding chains and locks to the operating wheels of these valves in such a manner that attempting to open either valve will cause the adjacent valve to rotate in the "close" direction. This technique will prevent the valve from being opened until the lock is removed.
- Locking a sleeve or cover placed over the valve operates so the valve can't be opened or closed until the sleeve or cover is removed.
- Starter controls on all pumps are to be locked in the "off" position when they are in nonoperating status. Only authorized personnel are to be allowed access to these controls.
- Loading/unloading connections of oil pipelines and facility piping are to be kept securely capped
 or blank-flanged when not in service or in standby service for an extended period of time. This
 may be accomplished by installing a valve at the end of a piping connection and enclosing the
 valve in a lockable box. Said box shall be so designed that the valve cannot be operated until
 the box is unlocked and opened.

By Rule, this facility is to be protected by deterrents, such as security fencing, that will discourage acts of vandalism. Fencing has been placed partially around the Facility. Additionally, the loading and unloading rack is placed undercover within a lockable garaged structure.

The facility has a security plan, written in accordance with 49 CFR 172. The U.S. Department of Transportation regulations for handlers or transporters of hazardous materials pertain to the facility's security requirements.

3.10 Tank Truck Loading/Unloading Rack Requirements (40 CFR 112.7 (h))Tank truck unloading procedures shall conform to all requirements established by the Department of Transportation.



3.10.1 Secondary Containment (40 CFR 112.7 (h)(1))

The operations at the facility do meet the EPA definition of a loading/unloading rack and therefore the truck unloading area is provided with secondary containment. The containment area has a capacity of 3.5 million gallons, which is adequate to contain the largest anticipated release from a bulk transfer vehicle loading at the facility. The location of the secondary containment area is shown in **Figure 2** (Appendix A) and the dimensions of the secondary containment area are included in Table 2-1.

3.10.2 Loading/Unloading Procedures (40 CFR 120.7 (h)(2) and (3))

All bulk petroleum suppliers must meet the minimum requirements and regulations for tank vehicle loading/unloading established by the U.S. Department of Transportation. The SPCC Plan Coordinator will ensure that bulk petroleum suppliers understand the site layout, know the protocol for unloading the product, and have the necessary equipment to respond to a discharge from the delivery vehicle.

The facility has implemented internal offloading procedures that personnel and delivery drivers must adhere to while transferring bulk oil deliveries to the facility. Tank truck unloading procedures shall conform to all requirements established by the Department of Transportation.

Tank truck loading/unloading activities are conducted within a loading earthen berm containment system. The approximate containment volume of this area is approximately 3.5 million gallons.

An interlocked warning light, physical barrier system, wheel chocks, or warning signs, or vehicle break interlock system is to be provided and at least one of these devices are to be used in loading/unloading areas to prevent vehicular departure before a complete disconnect of the flexible or fixed transfer lines has been made.

Prior to filling and departure of any tank truck, the lower-most drain and all outlets of such vehicles shall be closely examined for leakage and if necessary, tightened, adjusted, or replaced to prevent liquid leakage while in transit.

When tank trucks are not in use, they are emptied of their fuel and parked at the facility. No fuel is to be left in the tank truck when it is not in use during non-working hours. A notice to Tank Vehicle drivers is included in **Appendix M**.

3.11 Brittle Fracture Evaluation (40 CFR 112.7 (i))

Field constructed aboveground containers are to be evaluated for brittle fracture whenever they undergo a repair, alteration, reconstruction, or change in service that may affect the risk of a discharge or failure due to brittle fracture or other catastrophe. Field-constructed ASTs are utilized at this facility.

If a field-constructed container undergoes a repair, alteration, reconstruction, or a change in service that might affect the risk of a discharge or failure due to brittle fracture failure or other catastrophe, evaluate the container for risk of discharge or failure due to brittle fracture or other catastrophes, and as necessary, take appropriate action.

3.12 Conformance with State and Local Applicable Requirements (40 CFR 112.7 (j))

Conformance and non-conformance with the applicable requirements of 40 CFR Part 112 is addressed in each section throughout this Plan. The facility shall remain in compliance with all applicable local, state and federal guidance, rules, laws, and regulations.



3.13 Qualified Oil-filled Operational Equipment (40 CFR 112.7 (k))

The facility has oil-filled operational equipment, electrical transformers, which would meet the definition of "qualified" because they have not experienced a spill of more than 1,000 gallons at one time or two spills of more than 42 gallons in a year. However, the facility has provided general secondary containment so the alternative requirements for general secondary containment in 40 CFR 112.7(k)(2) will not be adopted. General secondary containment for electrical transformers includes active sorbent materials for the typical failure mode and most likely quantity of oil that would be discharged.



4.0 Discharge Prevention; Provisions for Onshore Facilities (Excluding Production Facilities)

4.1 Facility Drainage (40 CFR 112.8(b))

The exterior tanks at the Coastal Energy facility are either located within a concrete secondary containment structure or within the earthen berm retention pond containment area. Rainwater that collects in the secondary containment shall be inspected by facility personnel prior to draining to ensure that only oil-free water is discharged. Only the SPCC Plan Coordinator has authority to authorize a discharge of rainwater. If rainwater is released from the containment structure, the procedures in **Section 4.2.3** shall be followed.

4.2 Bulk Storage Containers (40 CFR 112.8(c))

All containers, including bulk containers, are summarized in Table 2.1 in Appendix L.

4.2.1 Construction (40 CFR 112.8 (c)(1))

All of the storage tanks and drums used for oil storage are constructed of either polyethylene, plastic, or steel, all of which are compatible with the petroleum products stored in the tank and containers. All oil storage tanks and drums operate at normal atmospheric conditions and none are pressurized.

4.2.2 Secondary Containment (40 CFR 112.8(c)(2))

All bulk oil storage tanks have secondary containment structures that are sized to contain the entire capacity of each tank, or the largest tank, plus sufficient freeboard to contain precipitation if located outside.

The materials of construction and storage volume for secondary containment structure at the Coastal Energy facility are listed on **Table 2-1 (Appendix L)**. The secondary containment structures are inspected on a routine basis.

It is recommended that management have the electrical installations inside the containment inspected by a licensed electrician at its earliest opportunity. Pumping motors and related electrical conduits are mounted inside the containment in a position where they may become submerged in petroleum products should a tank rupture occur. Electrical equipment should be inspected to verify it is intrinsically safe, i.e. explosion proof.

It is recommended that management periodically test the integrity of the containment systems by flooding them with water. If the containment will not hold water, management shall repair any leaks.

4.2.3 Drainage of Containment Structures (40 CFR 112.8(c)(3))

The containment structures that do not have a drain to discharge rainwater may utilize a pump system to discharge rainwater. If the water has no petroleum sheen, it may be released to the surface. If the water has petroleum sheen, the petroleum sheen shall be removed and disposed of in accordance with all applicable federal, state, and local laws and regulatory guidance. After the petroleum sheen has been removed the water contained in the tank may be released to the environment. The SPCC Plan Coordinator shall be the only personnel to possess the authority to authorize the collected rainwater to be pumped and discharged from the secondary containment area. These events shall be recorded on the "Rain Water Discharge from Containment" form that is included in **Appendix D**. As required by 40



approximately 45-feet underground. The piping consists of steel pipe and has a double walled protection system that overfills and alerts operators if the underground piping system has failed. The testing system consists of a ball valve regulator that is opened before and after each transfer to check for fugitive product. If fugitive product is not visible, the transfer from the rail car to the bulk storage tanks is initiated.

Although this section of pipe does not have cathodic protection it does meet the regulatory requirements of 40 CFR 280.40(a)(1) and (2). The system provides a method of release detection that can detect a release from any portion of the underground piping that routinely contains product. 40 CFR 280.44(c) indicates that any of the methods in 40 CFR 280.43 (e) through (f) may be used if they are designed to detect a release from any portion of the underground piping that routinely contains regulated substances. In accordance with 40 CFR 280.43(g), the system utilizes interstitial monitoring which is designed, constructed and installed to detect a leak from any portion of the [piping] that routinely contains product. Additionally, the double walled monitoring system used for this portion of underground piping, in accordance with 40 CFR 280.43(g)(1), is a double-walled [piping] system whereas the test method outlined can detect a release from the inner wall in a portion of the [piping] that routinely contains product.

4.2.5 Partially Buried and Bunkered Storage Tanks (40 CFR 112.8(c)(5))

This section is not applicable since there are no partially buried or bunkered storage tanks at this facility.

4.2.6 Inspections and Tests (40 CFR 112.8(c)(6))

Inspections and testing of the oil storage tanks and portable containers will be performed according to following procedures. Records of inspections and tests will be signed by the SPCC Plan Coordinator, or designee, and are required to be kept at the facility for at least three years. The facility must test or inspect their tanks for integrity on a regular schedule and whenever there are material repairs. The facility must determine, in accordance with industry standards, the appropriate qualifications for personnel performing tests and inspections, the frequency and type of testing and inspections, which take into account container size, configuration, and design. Examples of integrity tests include visual inspections, hydrostatic testing, radiographic testing, ultrasonic testing, acoustic emissions testing, or other systems of non-destructive testing.

For shop fabricated tank integrity tests, the facility will follow the latest edition of STI SP001 – Standard for the Inspection of Aboveground Storage Tanks (AST), currently the 5th Edition, 2011. Qualifications for inspectors are listed in SP001, Section 4.0. The Owners Inspector "shall be knowledgeable of storage facility operations, the type of AST and its associated components, and characteristics of the liquid stored." The inspection schedules are listed in Section 5.0 of SP001 and are based upon the AST's type, size, and type of installation. All tanks at the facility would be considered Category 1 AST's because they have both spill control (dikes or berms) and Continuous Release Detection Methods (CRDM) because they are elevated tanks with release prevention barriers (RPB) so that any releases can be visually detected. Table 5.5 in SP001 lists the type and frequency of inspections for Category 1 shop-fabricated tanks.

Shop fabricated tanks at the facility will be inspected according to the following types and frequencies:



Tanks at the facility with a capacity less than 5,000 gallons are designated as "P" (periodic AST inspections). Periodic AST inspections are defined as AST inspections conducted by the <u>owner's inspector</u>, meeting the required qualifications and include a monthly inspection checklist and an annual checklist.

Tanks at the facility larger than 5,000-gallons that were shop fabricated will be inspected according to the latest edition Steel Tank Institute (STI) STI SP001 – Standard for the Inspection of Aboveground Storage Tanks. This standard allows visual inspections to replace integrity testing by one of EPA's listed methods. The tanks are categorized as SP001 Category 1 tanks because they rest on a concrete slabs so that any leakage can be detected visibly and because they have a concrete containment structure. The type and frequency of inspections for these tanks are listed on Table 5.5 in SP001 for tanks between 5,000 gallons and less than 30,000 gallons. The requirements include completion of monthly and annual inspections by plant personnel and a Formal Exterior Inspection (FEI) performed by an API certified inspector every 20 years. The plant personnel performing monthly and annual inspections must meet the API qualifications for "owner's inspectors," which are they "shall be knowledgeable of storage facility operations, the type of AST and its associated components, and characteristics of the liquid stored."

Portable containers (drums) are to be inspected monthly if they have been on site for more than 91 days using the drum inspection checklist.

Integrity testing that is consistent with industry standards will occur immediately after <u>material repairs</u> are made to containers regardless of previous visual inspections as required by 40 CFR 112.8(c)(6).

Forms to document monthly and annual inspections, repairs, and tests performed on tank at the facility, are included in **Appendix C**, and can be used to record these activities.

Field-fabricated tanks are located at the facility and therefore, those tanks are subject to testing requirements as described in the American Petroleum Institute (API) document entitled "API Standard 653 – Tank Inspection, Repair, Alteration, and Reconstruction." All field fabricated tanks at the facility fall under the API 653 standard.

The API 653 standard covers carbon and low alloy steel tanks built to API standard 650 and its predecessor API12C. This standard provides minimum requirements for maintaining the integrity of welded or riveted, non-refrigerated, atmospheric pressure, aboveground storage tanks after they have been placed in service. It covers the maintenance, inspection, repair, alteration, relocation, and reconstruction of such tanks. The scope of the standard is limited to the tank foundation, bottom, shell, structure, roof, attached appurtenances, and nozzles to the face of the first flange, first threaded joint, or first welding-end construction.

The interval between inspections of a tank (both internal and external) should be determined by its service history unless special reasons indicate that an earlier inspection must be made. A history of the service of a given tank or a tank in similar service should be available so that complete inspections can be scheduled with a frequency commensurate with the corrosion rate of the tank. On-stream, nondestructive methods of inspection shall be considered when establishing inspection frequencies.



Jurisdictional regulations, in some cases, control the frequency and interval of the inspections. These regulations may include vapor loss requirements, seal condition, leakage, proper diking, and repair procedures. Knowledge of such regulations is necessary to ensure compliance with scheduling and inspection requirements. The facility shall maintain a complete record file consisting of three types of records, namely; construction records, inspection history, and repair/alteration history.

4.2.7 Heating Coils (40 CFR 112.8(c)(7))

Because the asphalt oils can attain temperatures of 350° Fahrenheit, the facility utilizes heating coils to regulate the internal temperature of the tanks containing asphalt oil. Coastal Energy shall control leakage through defective internal heating coils by monitoring the steam return and exhaust lines for contamination from internal heating coils that discharge into an open watercourse, or pass the steam return or exhaust lines through a settling tank, skimmer, or other separation or retention system

4.2.8 Overfill Prevention Systems (40 CFR 112.8(c)(8))

The petroleum tanks at the Coastal Energy facility are filled either by bulk tanker trucks, offloaded from rail cars, or the 55-gallon drums and 350-gallon totes are removed and replaced. The SPCC Plan Coordinator knows the level of petroleum in the tanks from use monitoring, visual inspection through the top of the tank and product level indicator methods. An oil delivery is requested when the tanks reach a certain level of product and tank deliveries shall be coordinated so that a full vehicle load delivery will not overfill the tanks. The SPCC Plan Coordinator or designee stays with the bulk delivery vehicle during product deliveries in accordance with the facilities work instruction. An inventory of all bulk ethanol and asphalt oil products is conducted daily and entered into a monitoring system by Coastal Energy employees.

Petroleum transfer operations from the bulk delivery trucks and rail cars to the petroleum tanks are permitted only after delivery piping is inspected for damage and proper connection, and valve paths have been inspected for proper valve positioning. Bulk petroleum vehicles shall be inspected by Coastal Energy facility personnel for leakage and proper valve positioning upon arrival at the site.

All loading and unloading procedures meet the minimum criteria specified in 49 CFR Part 177 Subpart B (Loading and unloading). Transfers start slowly to minimize potential for static discharge and to allow for initial checks for leakage. Transfer is monitored continuously by the bulk delivery vehicle drivers and Coastal Energy facility personnel. After the transfer is finished, drivers will wait at least one minute to allow any static discharge to dissipate. All remaining loading valves still in the open position are then closed and loading hoses or pipes disconnected. Where automatic drain-back or close-coupling is not provided, care is taken to prevent spillage from hoses or pipes upon disconnection.

4.2.9 Effluent Treatment Facilities (40 CFR 112.8(c)(9))

There is no effluent treatment facilities associated with this location.

4.2.10 Visible Discharges (40 CFR 112.8(c)(10))

Visible discharges from any container or appurtenance – including seams, gaskets, piping, pumps, valves, rivets, and bolts shall be quickly corrected upon discovery.

Oil is promptly removed from the secondary containment areas and disposed of according to the waste disposal method described in Part 5 of this Plan.



4.2.11 Mobile and Portable Containers (40 CFR 112.8(c)(11))

The facility has multiple 55-gallon drums and 350-gallon totes which are considered portable containers. Information for each container, including the type of petroleum product stored, storage capacity, and type of secondary containment is summarized in Table 2-1 (Appendix L).

4.3 Transfer Operations, Pumping, and In-Plant Processes (40 CFR 112.8(d))

Transfer operations at the Coastal Energy facility include the transfer of oil from contract vendor's bulk delivery trucks and rail cars into the bulk oil storage tanks and the transfer of ethanol and asphalt oil stored in tanks to contractors.

Transfer operations begin only after delivery piping is inspected for damage and proper connection, and valve paths have been inspected for proper valve positioning. Bulk oil trucks are inspected by operational site personnel for leakage and proper valve positioning upon arrival at the site. Bulk oil trucks are required to have equipment that will allow the immediate shutdown of transfer operations if necessary to prevent or mitigate spills. Corrective measures, if necessary, are made prior to commencing transfer operations. All loading and unloading procedures meet the minimum criteria specified in 49 CFR Part 177 Subpart B (Loading and unloading).

Transfers start slowly to minimize potential for static discharge and to allow for initial checks for leakage. Transfer is monitored continuously by the vehicle driver and Coastal Energy facility personnel. After transfer, drivers will wait at least one minute to allow any static discharge to dissipate. All remaining loading valves still in the open position are then closed and loading hoses or pipes disconnected. Where automatic drain-back or close-coupling is not provided, care is taken to prevent spillage from hoses or pipes upon disconnection.

Spill response equipment and materials are located in the emergency response trailer which is housed on-site, south of the training facility. Spill kits are stored throughout the facility and will be maintained in open view for ready access. The SPCC Plan Coordinator will mobilize equipment upon determination of need. The SPCC Plan Coordinator maintains the necessary spill recovery equipment and materials. An inventory of the spill recovery equipment will be taken monthly and after any spill event.

Through signage, the facility warns all vehicles entering the facility to be sure that no vehicle will endanger aboveground piping or other oil transfer operations. There is no need for cathodic protection since the only buried piping at the Coastal Energy facility is in compliance with 40 CFR 280, as described in Section 3.7.3. If underground piping is employed with the Coastal Energy facility that does not meet the requirements set forth in 40 CFR 112 and 40 CFR 280, it must be cathodically protected against corrosion.

All pipe supports are designed to minimize abrasion and corrosions and to allow for expansion and contraction. Pipe supports are visually inspected during the monthly inspection of the facility.

Oil and petroleum products shall be delivered to the Coastal Energy facility by a transport vehicle during hours when personnel are onsite. The transport vehicle tank and compartments are subject to inspection requirements of Department of Transportation 49 CFR, Part 180, §180.407, Requirements for



Test and Inspection of Specification Cargo Tanks, (c) Periodic Test and Inspection. This inspection consists of the following:

- External visual inspection All other cargo tanks, annually.
- Internal visual inspection All other cargo tanks with manholes, every 5 years.
- Leak test All other cargo tanks, annually.
- Pressure test All other cargo tanks, every 5-years.

Due to the inspection requirements, the potential for a discharge to originate from the tank of a transport vehicle is low. Therefore, the most likely spill to occur is transferring the product versus storing the product. If product delivery personnel are allowed to unload oil without the direct supervision of facility personnel, they will be provided a copy of Figure 2 - Site Layout and will be expected to review it noting the location of oil storage containers, equipment, above ground piping and other oil transfer features as required by 40 CFR 112.8 (d) (5). All valves and hoses will be inspected by the transport vehicle personnel. After initiating transfer operations, transport vehicle personnel will reinspect hose connections and fittings for any evidence of leakage. If a leak is visible, transport vehicle personnel will shut down the transfer system immediately, determine the cause of the leak, and repair the cause of the leak before resuming transfer operations. In the event of a discharge during loading operations, delivery personnel will immediately notify the SPCC Plan Coordinator or designee. Appendix M contains the Notice to Petroleum Delivery Personnel that includes preventative measures to ensure that tank delivery vehicles do not depart before completely disconnecting from an oil transfer line and that transport vehicle personnel fully inspect petroleum vehicles for discharges from lowermost drains and outlets to ensure that discharges do not occur while in transit.

Regulatory Requirements

- Transport vehicle loading and unloading procedures should meet the minimum requirements and regulations established by the Department of Transportation.
- A warning light, physical barrier system, or warning signs will be provided and used in loading/unloading areas to prevent vehicular departure before complete disconnect of flexible or fixed transfer lines. [40 CFR 112.7(h)(2)]
- Prior to filling and departure of any tank vehicle, the lower most drain and all outlets of such vehicles will be closely examined for leakage and if necessary, tightened, adjusted, or replaced to prevent liquid leakage while in transit. [40 CFR 112.7 (h) (3)]

Recommended Practices

- The SPCC Plan Coordinator, or designed personnel, will use pump meter readings and ullage records to accurately determine the liquid level in the tanks prior to loading to prevent an overfill.
- Schedule deliveries to the Coastal Energy facility only during hours when personnel are onsite.
- Store loading hoses within containment areas or inside the hose storage pipe when not in use.



5.0 Discharge Response

This section describes the response and cleanup procedures in the event of an oil discharge. An important facet of an effective response procedure during an oil discharge incident is to keep the material separated from water to minimize migration and the resulting potential increase in human and environmental exposure. Every effort shall be made to prevent a discharge and emphasize containment at the source rather than resort to separation of the material from expanded portions of the environment or downstream waters.

A commitment of manpower, equipment, and materials for discharge response is demonstrated by signing the Certification Information page at the beginning of the SPCC Plan by Coastal Energy facility management and taking an inventory of the containment and cleanup supplies. An agreement with a spill response contractor has not been implemented but a contractor may be used when responding to an oil discharge at this facility.

The Coastal Energy facility personnel shall provide appropriate clean-up and remediation on minor spills/releases. Supplies are maintained on-site in spill kits to stop and remediate a release of up to 50 gallons. If there were an incident that Coastal Energy facility personnel are not capable of handling, an outside contractor may be utilized. For spills that cannot be contained utilizing available materials, the Facility Emergency Response Plan shall be activated. As a client of Environmental Works, Inc. (EWI), Coastal Energy has access to EWIs 24-hour emergency response hotline and may utilize that service at any time.

A list of Emergency Contacts is provided in **Appendix H**. A list of discharge response material kept at the facility is included in **Appendix J**.

Upon observing a release, personnel on the scene shall take immediate steps to contain the spill and prevent product from reaching any body of water, including the Unnamed Tributary of the Eleven Point River and the Eleven Point River. If an unsafe condition has been created by a spill, or there is an immediate danger to human health, call 911. If the spill does not reach a waterway, you are not required to call MDNR per the Departments Notification Procedures.

When responding to a spill or a release, the main priorities are safety, minimization, containment, clean-up, and disposal. Proper safety equipment, which may include gloves, boots, protective suits, or respiratory protection, should be worn. The following health and safety practices and recovery techniques should be followed for maximum personnel safety and minimum equipment damage:

- Familiarize personnel with the MSDS of different materials used in their work area;
- In case of fire, the SPCC Plan Coordinator shall notify the Fire Marshal and ensure that evacuation of facility personnel is complete and adequate;
- All cleanup crew members shall be properly protected to prevent exposure to hazardous substances;
- Avoid use of cell phones unless they are certified as explosion proof;
- Do not divert the spill to storm or sanitary sewer lines;
- Do not trap volatile chemicals such as gasoline in underground structures such as storm and sanitary sewers;
- Do not linger around spill areas with chemical materials;



- Wash down spills only for safety purposes; and
- Use only explosion-proof pumps during cleanup operations.

5.1 Response to Minor Discharge

A "minor" discharge is defined as one that poses no significant harm (or threat) to human health and safety or to the environment. Minor discharges are generally those where:

- The quantity of product discharged is small (e.g., may involve less than 10 gallons of oil);
- Discharged material is easily stopped and controlled at the time of the discharge;
- Discharge is localized near the source;
- Discharged material is not likely to reach water;
- There is little risk to human health or safety; and
- There is little risk of fire or explosion.

Minor discharges can usually be cleaned up by facility personnel. The following guidelines apply:

- Immediately notify the Facility Manager.
- Under the direction of the Facility Manager, contain the discharge with discharge response materials and equipment. Place discharge debris in properly labeled waste containers.
- The Facility Manager will complete the discharge notification form (Appendix I) and attach a copy to this SPCC Plan.
- If the discharge involves more than 10 gallons of oil, the Facility Manager will call the Missouri Department of Natural Resources.

5.2 Response to Major Discharge

A "major" discharge is defined as one that cannot be safely controlled or cleaned up by facility personnel, such as when:

- The discharge is large enough to spread beyond the immediate discharge area;
- The discharged material enters water;
- The discharge requires special equipment or training to clean up;
- The discharged material poses a hazard to human health or safety; or
- There is a danger of fire or explosion.

In the event of a major discharge, the following guidelines apply:

All workers must immediately evacuate the discharge site via the designated exit routes and
move to the designated staging areas at a safe distance from the discharge. Exit routes are
included on the facility diagram and posted in the maintenance building, in the office building,
and on the outside wall of the outside shed that contains the spill response equipment.

If the SPCC Coordinator is not present at the facility, the senior on-site person notifies the Facility Manager of the discharge and has authority to initiate notification and response. Certain notifications are dependent on the circumstances and type of discharge. For example, if oil reaches a sanitary sewer, the publicly owned treatment works (POTW) should be notified immediately. A discharge that threatens waterways may require immediate notification to downstream users. The SPCC Coordinator (or senior on-site person) must call for medical assistance if workers are injured.

• The SPCC Coordinator (or senior on-site person) must notify the Fire Department or Police Department.



- The SPCC Coordinator (or senior on-site person) must call the spill response and cleanup contractors listed in the Emergency Contacts list in **Appendix H**.
- The SPCC Coordinator (or senior on-site person) must immediately contact the Missouri
 Department of Natural Resources (MDNR) and the National Response Center (888-424-8802).
- The SPCC Coordinator (or senior on-site person) must record the call on the Discharge Notification form in **Appendix I** and attach a copy to this SPCC Plan.
- The SPCC Coordinator (or senior on-site person) coordinates cleanup and obtains assistance from a cleanup contractor or other response organization as necessary.

If the SPCC Coordinator is not available at the time of the discharge, then the next highest person in seniority assumes responsibility for coordinating response activities.

5.3 Waste Disposal

Recovered oil, oil-impacted materials, and any oil contaminated debris will be disposed according to all applicable local, state, and federal regulations, laws, and guidance.

5.4 Discharge Notification

Any employee who observes a release should immediately report it to the designated personnel at the facility. The designated personnel must then immediately notify the spill/release information to the MDNR Emergency Response Unit. The reporting phone numbers can be found on the emergency contact list located in **Appendix H**.

A summary sheet is included in **Appendix I** to facilitate reporting. The person reporting the discharge must provide the following information:

- Name, location, organization, and telephone number
- Name and address of the party responsible for the incident
- Date and time of the incident
- Location of the incident
 Source and cause of the release or discharge
- Types of material(s) released or discharged
- Quantity of materials released or discharged
- Danger or threat posed by the release or discharge
- Number and types of injuries (if any)
- Media affected or threatened by the discharge (i.e., water, land, air)
- Weather conditions at the incident location
- Any other information that may help emergency personnel respond to the incident

In addition to the above reporting, 40 CFR 112.4 requires that information be submitted to the United States Environmental Protection Agency (EPA) Regional Administrator and the appropriate state agency in charge of oil pollution control activities (see contact information in **Appendix H**) whenever the facility discharges (as defined in 40 CFR 112.1(b)) more than 1,000 gallons of oil in a single event, or discharges (as defined in 40 CFR 112.1(b)) more than 42 gallons of oil in each of two discharge incidents within a 12-month period. The following information must be submitted to the EPA Regional Administrator and to MADEP within 60 days:

• Name of the facility;



- Name of the owner/operator;
- Location of the facility;
- Maximum storage or handling capacity and normal daily throughput;
- Corrective action and countermeasures taken, including a description of equipment repairs and replacements;
- Description of facility, including maps, flow diagrams, and topographical maps;
- Cause of the discharge(s) to navigable waters and adjoining shorelines, including a failure analysis of the system and subsystem in which the failure occurred;
- Additional preventive measures taken or contemplated to minimize possibility of recurrence;
 and
- Other pertinent information requested by the Regional Administrator.

The report must be submitted to the following address:

Regional Administrator, Region VII U.S. Environmental Protection Agency 11201 Renner Blvd. Lenexa, KS 66219

A standard report for submitting the information to the EPA Regional Administrator and to MDNR is included in **Appendix K** of this Plan. The Revised Statues of Missouri (RSMo) provides the following concerning a release:

- A "hazardous substance emergency" is defined in RSMo Chapter 260, Environmental Control, Section 260.500, Definitions (6) "Hazardous Substance Emergency" (b) as "Any release" (bold italics added for emphasis) of petroleumin excess of fifty gallons for liquids or three hundred cubic feet for gases."
- A "release" is defined in Section 260.500, Definitions (9) "Release" is any threatened or real
 emission, discharge, spillage, leakage, pumping, pouring, emptying or dumping of a substance
 into or onto the land, air or waters of the state unless done in compliance with the conditions of
 a federal or state permit, unless the substance is confined and is expected to stay confined to
 property owned, leased or otherwise controlled by the person having control over the
 substance, or unless, in the case of pesticides, if application is done in accordance with the
 product label."

Any spills or release of a petroleum product will be cleaned up, placed in a container and disposed of properly in accordance with the spill response procedures outlined in the SPCC Plan. Personnel will immediately contact the owner or his designee if the spill or release of any petroleum product leaves the property or enters water of the state.

5.5 Cleanup Contractors and Equipment Suppliers

The SPCC Plan Coordinator may utilize loaders, dozers, dump vehicles, aggregate stockpiles, and other equipment and materials available for containment or cleanup of oil spills or may use outside cleanup contractors and equipment suppliers for specialized spill response. Contact information for specialized spill response and cleanup contractors are provided in **Appendix H**. These contractors have the necessary equipment to respond to a discharge of oil that affects the facility.




APPENDIX A

Coastal Energy Corporation

APPENDIX A

Site Map & Facility Diagram



EWI# 140201 DRAWN BY: MEK Jul. 11, 2014


1000 2000

APPROXIMATE


ENVIRONMENTAL WORKS

1455 E. Chestnut Expressway, Springfield, MO 65802

1 COASTAL DRIVE WILLOW SPRINGS, HOWELL COUNTY, MISSOURI PERMIT# M00136883, SIC# 2951







APPENDIX B

Coastal Energy Corporation

APPENDIX B

Substantial Harm Determination

Substantial Harm Determination


Facility	Name:	Coastal Energy Corp	poration	
Facility .	Address:	1 Coastal Drive, Wil	low Springs, MO 65793	
If a facil	ity answers "Yes"	to any of these ques	tions, it will need a Facility Response Plan instead of a SPCC Plan.	
1.		transfer oil over wate than or equal to 42,0	er to or from vessels and does the facility have a total oil storage 000 gallons?	
	<u> </u>	Yes	No	
2.	facility lack seco	ndary containment the storage tank plus su	ge capacity greater than or equal to 1 million gallons and does the nat is sufficiently large to contain the capacity of the largest ficient freeboard to allow for precipitation within any above ground	oil
		Yes	No	
3.		ance such that a discl	ge capacity greater than or equal to 1 million gallons and is the facilit narge from the facility could cause injury to fish and wildlife and	у
	_	Yes	No	
4.			age capacity greater than or equal to 1 million gallons and is the faciliharge from the facility would shut down a public drinking water intak	
		Yes	<u> </u>	
5.	Does the facility experienced a reyears?	v have a total oil stora eportable oil spill in a	ge capacity greater than or equal to 1 million gallons and has the fac n amount greater than or equal to 10,000 gallons within the last five	ility
		Yes	<u>No</u>	
this do	cument, and that	based on my inquiry	CERTIFICATION conclude the contraction of those individuals responsible for obtaining this information, I contraction, and complete.	
Signat	ure		Date	
Name			Title	

APPENDIX C

Coastal Energy Corporation

APPENDIX C

Facility Inspection Checklists



Monthly Inspection Checklist - Bulk Oil Storage A1 - 30,000 Gallon Ethanol Tank A2 - 30,000 Gallon Ethanol Tank A3 - 30,000 Gallon Ethanol Gallon Ethanol Gallon Ethanol Gallon Ethanol A4 - 30,000 A5 - 30,000 A6 - 30,000 Comments Yes-No-N/A Yes-No-N/A Yes-No-N/A Yes-No-N/A Item 1.0 Tank Containment 1.1 Is there water, debris, cracks or a fire hazard within the containment structure? 1.2 Is water located around the primary tank? 1.3 Are the containment drain valves operable and in a closed position? 1.4 Are the pathways and entry clear and gates/doors operable? 2.0 Leak Detection 2.1 Does the tank have visible signs of leakage? 2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment? 2.3 Does the surrounding soil have visible signs of leakage? 2.4 Does the interstice have visible signs of leakage? 3.0 Tank Equipment 3.1(a) Are the tank valves free from leaks? 3.1(b) Are the tank valves locked? 3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present? 3.2(b) Are the drain valves on the spill containment boxes and fill pipes operable and closed? 3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage. 3.3(b)The liquid level equipment device is easily readable. 3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed. 3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation. 3.5 Check for leaks, corrosion and damage to the piping conections. 4.0 Tank Attachments and Appurtenances 4.1 Is the ladder and platform structure secure with no signs of severe corrosion or damage? 5.0 Other Conditions 5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?

1. This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.

Inspection Date:

Inspectors Printed Name:

Inspectors Signature:

4. The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly

^{5.} In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

Monthly Inspection Checklist - Bulk						Storage			
ltem.	A7 - 30,000 G Gallon Ethanol	A8 - 30,000 G Gallon Ethanol Tank	A9 - 30,000	A10 - 30,000	# F1 - 20,000 G Gallon Fusel Z Tank	유 F2 - 20,000 호 Gallon Fusel 조 Tank	Comments		
1.0 Tank Containment				Tallian Santa Commit	W-100 III				
1.1 Is there water, debris, cracks or a fire hazard within the containment structure?		le derhantant.		Colombias	ESIZA IA	Mary Zone	part value men - a minute		
1.2 Is water located around thr primary tank?					1100	knowl e 40 to	and become have and		
1.3 Are the containment drain valves operable and in a closed position?					All money files	iki cidadi	Region at the first on the l		
1.4 Are the pathways and entry clear and gates/doors operable?				140	and agen	Assurbates Li	er alleria en la companya		
2.0 Leak Detection		SI-DINE S	Mark Town	THE PARTY OF	I Transaction				
2.1 Does the tank have visible signs of leakage?	901	1			egaleet	Comment of	correspondence (13)		
2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment?				1-40	MCB (FOLV)	Harry III	Control Provide Control of Contro		
2.3 Does the surrounding soil have visible signs of leakage?				3.5.2	arma Stage	in opinion and	The state of the s		
2.4 Does the interstice have visible signs of leakage?	atal ()			NATION AND DESCRIPTION OF THE PERSON OF THE	es comá				
3.0 Tank Equipment			TERM DE	NAME OF STREET	4				
3.1(a) Are the tank valves free from leaks?	EVER UNIT	1/1				and the second			
3.1(b) Are the tank valves locked?				75.0		(Allien)	the late of the second		
3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present?	1				inpolice of the second	broat.	pales discount — 1945 Southaire Services		
3.2(b) Are the drain valves on the spill containment boxes and fill pipes operable and closed?					n man qual Tri	kes fills coba am	may ten Sundamon, phil maps (may) 1012 - all second		
3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage.				- 11 -0 - 12	(4794 - 11890) - (401 - 01890)	Discharge Strip Jesus	yte myst the activity territory, and committee to the committee of the com		
3.3(b)The liquid level equipment device is easily readable.					Valency et	Walland Co.	S ANNUAL SERVICE SERVICES		
3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed.					Allone Today	Argus Maria Promitina Sept. — Promitina Promitina	Harmon and Arrenny Harmon Control Control A Strong STR Control B		
 3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation. 		4				aedyn 621	ritaria di Santana di Angala Santa di Santana Santa Santana di Santa		
3.5 Check for leaks, corrosion and damage to the piping conections.				15.036	المشاركان		reconstruction and a		
4.0 Tank Attachments and Appurtenances					11111010	12 Kg 7/15			
4.1 is the ladder and platform structure secure with no signs of severe corrosion or damage?	148.75	DOM:		25		Shiao William	September 2003		
5.0 Other Conditions				1000.00	10 80 Julio				
5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?					THE PROPERTY.	MITARIO DA	Special trace state to see and consistent		

Inspectors Printed Name:	Inspectors Signature:	

Inspection Date:

^{1.} This Monthly inspection Checklist follows Steel Tank Institute SP001 checklist guidance.
2. This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be

performed by a certified inspector.

3. Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly.

^{4.} The completed checklists must be maintained for 36 months howver, internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

	Mont	hly Inspect	ion Checkli	st - Bulk Oil	Storage		Market Min - 13 lettern 120	
	Tank 1 - 30,000 Gallon Asphalt Oil Tank	Tank 2 - 30,000 Gallon Asphalt Oil Tank	Tank 3 - 30,000 Gallon Asphalt Oil Tank	Tank 4 - 30,000 Gallon Asphalt Oil Tank	Tank 5 - 30,000 Gallon Asphalt Oil Tank	Tank 6 - 30,000 Gallon Asphalt Oil Tank	Total C	
Item	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments	
1.0 Tank Containment							mid macuum amakka 2002 salema	
1.1 Is there water, debris, cracks or a fire hazard within the containment structure?			K-m-e			Total Constitution	ella contenta consentati	
1.2 Is water located around thr primary tank?			T		The section	Santa	Commence of the Commence of th	
1.3 Are the containment drain valves operable and in a closed position?	41				Throat I	ing an am	Directions opening the Market	
1.4 Are the pathways and entry clear and gates/doors operable?			STEEL		The same			
2.0 Leak Detection	(Handi							
2.1 Does the tank have visible signs of leakage?	INCOME.				Mary State	in this A tension	pulmanan kersesa ing palah Per	
2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment?			_ = 4		1 40	San N	and paragraph of the star	
2.3 Does the surrounding soil have visible signs of leakage?	wines when			Serve a serve	10000		elviso in martini, in concept dia si	
2.4 Does the interstice have visible signs of leakage?		SA SEE	2577 248		177, 18940	Mark State	Mark Mark Andrewski	
3.0 Tank Equipment			10000100			STATE		
3.1(a) Are the tank valves free from leaks?		4 1	- 10	2,		134	Biggs on plant with a supplier of the first	
3.1(b) Are the tank valves locked?					. India	CET TO S	Consolida Alfre ou course de la consolida de l	
3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present?					i ten	Philosophia Taken	O contract on p 4 ca economic contract beauty	
3.2(b) Are the drain valves on the spill containment boxes and fill pipes operable and closed?					Ly (2)	And the same	ming that files the mind of the second of th	
3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage.					1	The expels	an analysis to the	
3.3(b)The liquid level equipment device is easily readable.					1	- wein	Artist or United to the State of the State o	
3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed.					a profession	all constant	Propose policina de la company	
3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation.	Table 1					1000	Partie of a principle	
3.5 Check for leaks, corrosion and damage to the piping conections.								
4.0 Tank Attachments and Appurtenances								
4.1 Is the ladder and platform structure secure with no signs of severe corrosion or damage?					1		284 284 cm = 9 20 ds	
5.0 Other Conditions	WAY THE	03000						
5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?								

Inspection Date:

Inspectors Printed Name:

^{1.} This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly.

^{4.} The completed checklists must be maintained for 36 months howver, internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

		Monthly Inspe	ection Checkli	st - Bulk Oll St	orage		
Control of the contro	Tank 7 - 210,000 Galon Asphalt Oil Tank	Tank 8 - 420,000 Gallon Asphalt Oil Tank	Tank 9 - 420,000 Gallon Asphalt Oil Tank	Tank 10 - 420,000 Gallon Asphalt Oll Tank	Tank 11 - 420,000 Gallon Asphalt Oil Tank	Tank 12 - 30,000 Gallon Asphalt Oil Tank	
ltem	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
1.0 Tank Containment	METODA III CA					r	
1.1 is there water, debris, cracks or a fire hazard within the containment structure?		BURES.			Hardist Lights 2		part in animal and
1.2 Is water located around thr primary tank?	+	1			- 1		Carte Cronsmission (est
1.3 Are the containment drain valves operable and in a closed position?					23.4643	Amort C. La	grafie seasonathing a state
1.4 Are the pathways and entry clear and gates/doors operable?							"martic (TMC I)
2.0 Leak Detection	Tribation to			Avenue de la companya			
218 4 11 21	PER LINE	NAME OF THE PARTY	The same	A SECTION AND ADDRESS OF THE PARTY OF THE PA	NEW YORK WAY	14 E E E E	
2.1 Does the tank have visible signs of leakage?		5 31 5 4					Commence of the commence of th
2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment?					1 spaces accelerates	branive shall experiencions	Ta haden theirs effected
2.3 Does the surrounding soil have visible signs of leakage?	1			4 10	Prediction (in bern	INASEC III THE THE PROPERTY OF THE
2.4 Does the interstice have visible signs of leakage?	į.				102124610	ni owalazy	and an above following of A
3.0 Tank Equipment		CE LEGATIN	STATE OF THE PARTY.				
3.1(a) Are the tank valves free from leaks?				Carried States	CONTRACTOR	5 De la	ERMICEL SELEMBERT CONTROL
3.1(b) Are the tank valves locked?		C. LORESE	100000	E Taran	2/7/2020/08/		POST CONTRACTOR CONTRACTOR
3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present?	J.					Meaning	March and Color of All Co
3.2(b) Are the drain valves on the spill containment boxes and fill pipes operable and closed?		1		-	Samuel And	nacci obser- elibrandum	Proposed edition (C.E.)
3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage.					agametanath To	bissimos is au par ele	terral transfer a (p.)
3.3(b)The liquid level equipment device is easily readable.				- 11	- ledev	ele ix-si	portion of the property of the
3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed.					RMELS	Leva Con ingle	the state of the s
3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation.				e l	and the past		The state of the s
3.5 Check for leaks, corrosion and damage to the piping conections.	1	i h	- h	- Same	Carlo Antonio de la	() when he	control of the contro
4.0 Tank Attachments and Appurtenances					No la compa		
4.1 Is the ladder and platform structure secure with no signs of severe corrosion or damage?					oit a start man	مالا برا بدالتا عا	Modifyla Davis architectura
5.0 Other Conditions	CAS THE	DESERTING OF					
5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?						one file	

 $1. \ This \ Monthly \ Inspection \ Checklist \ follows \ Steel \ Tank \ Institute \ SP001 \ checklist \ guidance.$

Inspectors Printed Name:

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly.

4. The completed checklists must be maintained for 35 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

Monthly Inspection Checklist - Bulk Oil Storage 30,000 Gallon Asphalt Oil Tank 13 -30,000 Gallon Asphalt Oil 30,000 Gallon Asphalt Oil 30,000 Gallon Asphalt Oil 30,000 Gallon olymer Tank 30,000 Gallon Jolymer Tank Fank 16 -Fank 18 -Fank 15 -Comments Yes-No-N/A Yes-No-N/A Yes-No-N/A Yes-No-N/A Yes-No-N/A 1.0 Tank Containment 1.1 Is there water, debris, cracks or a fire hazard within the containment structure? 1.2 Is water located around thr primary tank? 1.3 Are the containment drain valves operable and in a closed position? 1.4 Are the pathways and entry clear and gates/doors operable? 2.0 Leak Detection 2.1 Does the tank have visible signs of leakage? 2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment? 2.3 Does the surrounding soil have visible signs of leakage? 2.4 Does the interstice have visible signs of leakage? 3.0 Tank Equipment 3.1(a) Are the tank valves free from leaks? 3.1(b) Are the tank valves locked? 3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present? 3.2(b) Are the drain valves on the spill containment boxes and fill pipes operable and closed? 3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage. 3.3(b)The liquid level equipment device is easily readable. 3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed. 3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation. 3.5 Check for leaks, corrosion and damage to the piping conections. 4.0 Tank Attachments and Appurtenances 4.1 Is the ladder and platform structure secure with no signs of severe corrosion or damage? 5.0 Other Conditions 5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?

Inspectors	Printed	Name:
------------	---------	-------

Inspection Date:

^{1.} This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly.

^{4.} The completed checklists must be maintained for 36 months howver, Internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

Coastal Energy - SPCC Plan Monthly Inspection Checklist - Bulk Oil Storage 30,000 Gallon Asphait Oil Tank 30,000 Gallon Asphalt Oil Tank Tank 21 -30,000 Gallon Asphalt Oil Tank 22 -30,000 Gallon Asphalt Oil Tank 23 -30,000 Gallon Asphalt Oil Tank Tank 24 -30,000 Gallon Asphalt Oil Tank Tank 20 -Comments 10 Tank Containment 1.1 is there water, debris, cracks or a fire hazard within the containment structure? 1.2 is water located around thr primary tank? 1.3 Are the containment drain valves operable and in a closed position? 1.4 Are the pathways and entry clear and gates/doors operable? 2.0 Leak Detection 2.1 Does the tank have visible signs of leakage? 2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment? 2.3 Does the surrounding soil have visible signs of leakage? 2.4 Does the interstice have visible signs of leakage? 3.0 Tank Equipment 3.1(a) Are the tank valves free from leaks? 3.1(b) Are the tank valves locked? 3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present? 3.2(b) Are the drain valves on the spill containment boxes and fill pipes operable and closed? 3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage. 3.3(b)The liquid level equipment device is easily readable. 3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed. 3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation. 3.5 Check for leaks, corrosion and damage to the piping conections. 4.0 Tank Attachments and Appurtenances 4.1 is the ladder and platform structure secure with no signs of severe corrosion or damage? 5.0 Other Conditions 5.1 Are there other conditions that should be

Inspection Date:	Mary H

addressed for continued safe operation or that may

Inspectors Printed Name:

affect the site SPCC plan?

^{1.} This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly.

^{4.} The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, i.e., wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

- twings	Q25(20) 00	Monthly Inspe	ection Checkli	st - Bulk Oil St	orage		
	Tank B1 - 12,000 Gallon Diesel Tank	Diesel Tank 1 - 6,000 Gallon Diesel Tank	Diesel Tank 2 - 17,500 Gallon Diesel Tank	Used Oil - 1,100 Gallon Used Oil Tank			
ltem ltem	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
1.0 Tank Containment		1-17				Carlo Carlo Carlo	
1.1 Is there water, debris, cracks or a fire hazard within the containment structure?	4						As a promotion of
1.2 Is water located around thr primary tank?				de de	EV. H. HOL	THE STREET	efulpotente a l'Ul
1.3 Are the containment drain valves operable and in a closed position?					Spanie 200		// 1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/
1.4 Are the pathways and entry clear and gates/doors operable?	ENEXUPER C	O AND AND	DEAL OF U	demestra	VI. IUSELAN	MAL SEL	Day Te water
2.0 Leak Detection							
2.1 Does the tank have visible signs of leakage?	4	III I		(La)		2-7-70	Emples of the Control
2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment?					Service II de IV	and the	Brichard Aprila 5
2.3 Does the surrounding soil have visible signs of leakage?	10 -				Lineway a	315070-74	mile second of
2.4 Does the interstice have visible signs of leakage?	SECTION	Etc.	1475_1F		TELLE		PERSONAL PROPERTY.
3.0 Tank Equipment							
3.1(a) Are the tank valves free from leaks?						1452 (340)	A Hart Charles (1995)
3.1(b) Are the tank valves locked?				1	ampadasis Sanaga sa	elips to religio	Allocation wildings - 1
3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present?				2		rate of the control o	End of the problem
3.2(b) Are the drain valves on the spill containment boxes and fill pipes operable and closed?					A Marian Legent A Mil	internal section Security Section	To the second se
3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage.	1				THURSE		man had to Add to a specific before
3.3(b)The liquid level equipment device is easily readable.				- 1	To his Land of the		Maria Service
3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed.					AND THE RESERVE	to a militare term of site	Control of the contro
3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation.	4503/2					SAJEEN	g sale
3.5 Check for leaks, corrosion and damage to the piping conections.	PER NAME	BEKAKUVA	705	Costo Adia	in a	Feet (Feet)	
4.0 Tank Attachments and Appurtenances							
4.1 Is the ladder and platform structure secure with no signs of severe corrosion or damage?		H. C.			Car Carle		ALCOHOLOGICAL
5.0 Other Conditions							
5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?							1000 NOSCHEDI

Inspection (Date:
--------------	-------

Inspectors Printed Name:

^{1.} This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly.

4. The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

and the second of the second o	Mo	onthly Inspect	ion Checklist	- Oil Fiiled Eq	uipment		A
	Emergency Backup Generator - 400 Gallon	Used Oil Heater - 250 Gallon	And Tracking	12.00			
ltem	Yes-No-N/A	Yes-Na-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
1.0 Tank Containment							
1.1 Is there water, debris, cracks or a fire hazard within the containment structure?			9		family ma	100 11 11 70	EC-Secular exists [1]
1.2 Is water located around thr primary tank?	9			1		nety number	Plant of the second
1.3 Are the containment drain valves operable and in a closed position?		150			Section 1	and the section	(And the continue of the Additional Continue of
1.4 Are the pathways and entry clear and gates/doors operable?					2.93000	a back so a	In the organization of the contract of the con
2.0 Leak Detection							
2.1 Does the tank have visible signs of leakage?						100 N N N N N N N N N N N N N N N N N N	
2.2 Does the secondary containment have visible signs of leakage from any tank into secondary contianment?				+	Terre day	Super orin	Carrier absorptions, Page 15
2.3 Does the surrounding soil have visible signs of leakage?			1 - 1		14		
2.4 Does the interstice have visible signs of leakage?				Et w		Se liverier	Service Committee Committe
3.0 Tank Equipment					Roserva		
3.1(a) Are the tank valves free from leaks?						Philip	711.194479.75
3.1(b) Are the tank valves locked?						1124	Chrom water and space
3.2(a) Has the spill containment boxes on fill pipes been inspected for debris, residue, and water in the box and removed if present? 3.2(b) Are the drain valves on the spill containment					II .	IN ₁	and the real of the second section of the sect
boxes and fill pipes operable and closed?					-	de la company	in the Part of the San San San
3.3(a)The liquid level equipment, both visual and mechanical devices, have been inspected for physical damage.						Tech	Publiment programmes a level
3.3(b)The liquid level equipment device is easily readable.					a Valyard	d'Acquipeut	reform months are seg-
3.4(a) If overfill equipment is equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery operated. Replace the battery if needed.			eto.			ir anka	ACTION OF THE PERSON OF THE PE
3.4(b) If overfill valve is equipped with a mechanical test mechanism, actuate the mechanism to confirm operation.					midfair su-più	of the Control of	
3.5 Check for leaks, corrosion and damage to the piping conections.						investigation	Ment and the second
4.0 Tank Attachments and Appurtenances		THE REAL PROPERTY AND ADDRESS OF THE PARTY AND			GTAISH	TOTAL MARK	
4.1 Is the ladder and platform structure secure with no signs of severe corrosion or damage?					Lafe.	Marin Marin	and the second second
5.0 Other Conditions 5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?				100		The state of the s	

lns	ne	rtio	nΓ	ate	

Inspectors Printed Name:

^{1.} This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance,

² This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

3. Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid

for oil and sheens and remove and dispose of properly.

4. The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, i.e., wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

	Mo	nthly Inspe	ection Chec	klist - Trans	tormers	files.	
ltem	Yes-No-N/A	7- Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
.0 Tank Containment	Tes-NO-N/A	Yes-NO-N/A	Tes-NO-N/A	Tes-NO-N/A	TES-IND-IN/A	TES-NO-N/A	Continents
.1 Is there water, debris, cracks or a fire hazard within ne containment structure?						(PA)	
.2 Is water located around thr primary tank?	u l	195				120	
3 Are the containment drain valves operable and in a osed position?		拥		1 1		(31)	
4 Are the pathways and entry clear and gates/doors perable?	19	USI USI					
0 Leak Detection	19.1116						
1 Does the tank have visible signs of leakage?	51			Section 1			make have the best training
.2 Does the secondary containment have visible signs fleakage from any tank into secondary contianment?					7		
.3 Does the surrounding soil have visible signs of cakage?		300					A. A. A.
4 Does the interstice have visible signs of leakage?	40					The second	0
0 Tank Equipment						NAME OF	
1(a) Are the tank valves free from leaks?		10					184 184
.1(b) Are the tank valves locked?	8.0						Materiale)
2(a) Has the spill containment boxes on fill pipes been spected for debris, residue, and water in the box and emoved if present?		181					American III. 153 T. 22 SARSON IV. NO.
2(b) Are the drain valves on the spill containment oxes and fill pipes operable and closed?						Land	remarks to the Land
.3(a)The liquid level equipment, both visual and nechanical devices, have been inspected for physical amage.							PORT OF THE STATE
.3(b)The liquid level equipment device is easily eadable.							enu E
.4(a) If overfill equipment is equipped with a "test" utton, activate the audible horn or light to confirm peration. This could be battery operated. Replace the attery if needed.							65 America 127
.4(b) If overfill valve is equipped with a mechanical est mechanism, actuate the mechanism to confirm peration.							allon T 2
5 Check for leaks, corrosion and damage to the piping onections.	Pad		-			E AL	American designation of the second
0 Tank Attachments and Appurtenances		The state of					
.1 is the ladder and platform structure secure with no igns of severe corrosion or damage?			5 3		9 - 2		
.0 Other Conditions	44 01					1 4 4 1 1 1	
5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site SPCC plan?				THE STATE OF			1

Inspection Date:

Inspectors Printed Name:

^{1.} This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for oil and sheens and remove and dispose of properly.

^{4.} The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{5.} In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), an inspection of these components is required immediately following the event.

Portable Container Monthly Inspection Checklist - Totes Motor Oil - 120 Gallon Portable Tanks (X2) Motor Oil - 55 Gallon Drum (Multiple) Gallon Drum (Multiple) Gear Oil - 55 Hydraulic Oil (Multiple) 55 Gallon Item Yes-No-N/A Yes-No-N/A Yes-No-N/A Yes-No-N/A Comments 1.0 AST Containment/Storage Area 1.1 Portable containers within designated storage area? 1.2 Debris, spills, or other fire hazards in containment or storage areas? 1.3 Water in outdoor secondary containment? 1.4 Drain valves operable and in a closed position? 1.5 Egress pathways clear and gates/doors operable? 2.0 Leak Detection 2.1 Visible signs of leakage around the containers or storage area? 3.0 Containers 3.1 Noticeable container distortions, buckling, denting, or bulging?


Inspectors Printed Name:	Inspectors Signature:	- 単

Inspection Date:

^{1.} This Monthly Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.



Coastal Energy - SPCC Plan Annual Inspection Checklist - Bulk Oil Storage

	- Allina	ar mapeette	n Checklist	- bulk Oil	Storage		
ltem	A1 - 30,000 Gallon Ethanol Tank	유 A2 - 30,000 즉 Gallon Ethanol 국 Tank	A3 - 30,000	A4 - 30,000 Gallon Ethanol Tank	A5 - 30,000	A6 - 30,000	Comments
1.0 Tank Containment	TES-NO-N/A	TES-NO-N/A	162-140-14/A	TES-190-19/A	Tes-140-14/A	Tes-No-N/A	Comments
1 1 is the containment structure free from; holes or cracks in the containment wall or floor, washout, liner degradation, corrosion, leakage, paint failure and tank settling?					, iv		
2.0 Tank Foundatation and Supports							
2.1 Evidence of tank settlement or foundation washout?						10.00	
2.2 Cracking or spalling of concrete pad or ring wall?							
2.3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.?		4.72		47			
2.4 Water able to drain away from tank?							
2 5 Grounding strap secured and in good condition?							
3.0 Gathodic Protection							
3.1 Is the CP system functional and includes the wire		W. 19			2 7/1	12610	Lake the transfer of the second
connections for galvanic systems?	BEY ME	H. Lette		- Trib	Estado A	2.50	
3 2(a) Operational components (power switch, meters and alarms) been inspected for working condition?							
3 2(b) If applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current							
system.	COLORES .	0.000.00	526,250,637		20017-020	PACES	
4.0 Tank Shell, Heads and Roof		1	MEN ES				ALCOHOLOGICAL CONTRACTOR
4.1 Evidence of paint failure?		C.					
4 2 Are there any, dents, buckling, bulging, corrosion or cracking in the steel of the tank?				4			Jones Land
4.3 Is there low points or stading water on the roof slope?		1,0					
5.0 Tank Equipment						BHILL	
5.1 Vents: Verify that components are moving freely and vent passageways are not obstructed for. Emergency vent covers, pressure/vacuum vent poppets and other moving vent components.							
5 2 Valves: Check the condition of all valves for leaks,							TEN TO THE RESERVE OF THE PERSON OF THE PERS
corrosion and damage. 5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation.					7		
5.2.2 Pressure regulator valve: Check for proper operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not visible by looking from above only.)							1
5.2.3 Expansion relief valve. Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or tubing.)							
5.2.4 Solenoid valves: Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)							
5.2.5 Fire and shear valves: (a) Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to close completely. (b) Valves must not be wired in open position. (c) Make sure fusible element is in place and correctly positioned. (d) Be sure test ports are sealed with plug after testing is complete and no temporary test fixture or component remains connected to valve.							

v e	A1 - 30,000 Gallon Ethanol Tank	A2 - 30,000 Galion Ethanol Tank	A3 - 30,000 Gallon Ethanol Tank	A4 - 30,000 Gallon Ethanol Tank	A5 - 30,000 Gallon Ethanol Tank	A6 - 30,000 Gallon Ethanol Tank	
	A1 - 3 Gallo Tank	A2 - 3 Galio Tank	A3 - 3 Gallor Tank	A4 - 3 Gallo Tank	45 - 3 Sallo Fank	Sallor Fank	= = =
Item Land 144 and 1	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
5.3 Interstitial leak detection equipment: Check condition of equipment, including; the window is clean and clear in sight leak gauges, the wire connections of electronic gauges for tightness and corrosion, activate the test button, if applicable.			FINEE I				
5.4 Spill containment boxes on fill pipe: (a) If corrosion damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit. (b) Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary. (c) Drain valves must be operable and closed.							
5.5 Strainer: (a) Check that the strainer is clean and in good condition. (b) Access strainer basket and check cap and gasket seal as well as bolts.	28 178	prima	THE PARTY				a decay.
5.6 Filter: (a) Check that the filter is in good condition and is within the manufacturers expected service life. Replace if necessary. (b) Check for leaks and decreased fuel flow.						H I I I	
5.7 Flame arrestors: Follow manufacturer's instructions. Check for corrosion and blockage of air passage			egilora	ind positi			at a programme and a programme
5.8 Leak detector for submersible pump systems: Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.					mi cosp		Europe de marchine
5.9 Liquid level equipment: (a) Has equipment been tested to ensure proper operation? (b) Does equipment operate as required? (c) Follow manufacturer's instructions.	8.715		en an				
5.10 Overfill equipment: (a) Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification. (b) Confirm device is suited for above ground use by the manufacturer.							
6.0 Insulated Tanks				5.031.35			
6.1 Insulation: Check condition of insulation for; missing sections, areas of moisture, mold and damage.					7.4		Line of the second
6.2 Insulation cover or jacket: Check for damage that will allow water intrusion.					ning growt grown fiel		S. HORSAND
7.0 Miscellaneous 7.1 Electrical wiring and boxes: Are they in good condition?							-1.3 2.577
7.2 Labels and tags: Ensure that all labels and tags are intact and readable.		1.		[Lower			(a) 3-y-

Inspection Date:

Inspectors	Printed	Name:

Inspectors Signature:

1. This Annual Inspection Checklist follows Steel Tank Institute SP001 checklist guidance

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Inspect the AST shell and associate piping, valves, and pumps including inspection of the coating for paint failure.

^{4.} Inspect: Earthen containment structures including examination for holes, washout, and cracking in addition to liner degradation and tank settling. Concrete containment structures and tank foundations/supports including examination of holes, washout, settling, paint failure, in addition to examination for corrosion and leakage. Steel containment structures and tank foundations/supports including examination for washout, settling, cracking, and for paint failure, in addition to examination for corrosion and leakage.

^{5.} Inspection of cathodic protection system, if applicable, includes the wire connections for galvanic systems, and visual inspection of the operational components (power switch, meters, and alarms) of impressed current systems.

^{6.} Remove promptly upon discoverty standing water or liquid in the primary tank, secondary containment area, interstice, or spill container. Before discharge to the environment, inspect the liquid for oil or sheen and dispose of properly.

^{7.} In order to comply with EPA SPCC rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8©(8)(v

^{8.} The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five year:

^{9.} Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checlists

^{10.} Note: If change has occurred to the tank system or containment that may affect the SPCC Plan, the should be evaluated against the current plan requirement by a Professional Engineer knowledgable in SPCC development and implementation.

Page 12 of 37

Coastal Energy - SPCC Plan
Annual Inspection Checklist - Bulk Oil Storage

*	Annu	al Inspecti	on Checklis	t - Bulk Oil	Storage		
ltem .	A7 - 30,000	A8 - 30,000	A9 - 30,000	A10 - 30,000	F1 - 20,000 Sellon Fusel Tank	F2 - 20,000	Comments
1.0/Tank Containment					A CONTRACTOR		5-1-1-1-1-1-21 1-1-1-2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
1.1 is the containment structure free from, holes or		18	417			F-14 AU	La GENT HER AND ALEMAN AND AND AND AND AND AND AND AND AND A
cracks in the containment wall or floor, washout, liner					1.55 (1.51)	in fill within	PLO SHAPPING TO BUILD ON
degradation, corrosion, leakage, paint failure and tank settling?	1				IIIQU	MARKY L	Carrier Project Control
2.0 Tank Foundatation and Supports					like I resul		
2.1 Evidence of tank settlement or foundation				15	et ment		PARTY OF THE PROPERTY OF THE PARTY OF THE PA
washout?						1.4164	BALL THE LOND OF THE STREET
2.2 Cracking or spalling of concrete pad or ring wall?	1		1			Tall parties	MILES SOCIETA BOOKS (71)
2.3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.?			11			10 00	
2.4 Water able to drain away from tank?				7 19	=41	_	THE DISCORDED IN THE
2.5 Grounding strap secured and in good condition?			- 1	- 19	rya runi:	2 1 1 1 1 1	tile general masses
3.0 Cathodic Protection			Dinkers &				
3.1 Is the CP system functional and includes the wire		1		TE		100	STATE OF THE PARTY
connections for galvanic systems?	111				2820 . 1	N III	Personal Property and Company of the
3.2(a) Operational components (power switch, meters and alarms) been inspected for working condition?	ŶĮ.				10	100	William Committee
3.2(b) If applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current							r light light
system.	41				-211	2,111	Service Control of the Control of th
4.0 Tank Shell, Heads and Roof			e/femtets				
4.1 Evidence of paint failure?			1	1.00			Act and the second of the seco
4.2 Are there any, dents, buckling, bulging, corrosion or cracking in the steel of the tank?				1 1	F 92] [[] [dr.	Dept. (III) 6 - Mary 107 (III) y Mary
4.3 Is there low points or stading water on the roof slope?							
5.0 Tank Equipment		STATE OF					
5.1 Vents: Verify that components are moving freely							
and vent passageways are not obstructed for: Emergency vent covers, pressure/vacuum vent poppets and other moving vent components.							Side and the second
5.2 Valves: Check the condition of all valves for leaks,							
corrosion and damage.					200		Strain of the Control of the Control
5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation.					(7)	er de As	de en field Harm and vell
5 2.2 Pressure regulator valve: Check for proper				SOLD OF	- 999		
operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not visible by looking from above only.)						Mary and	According to the Post Samuel To
5.2.3 Expansion relief valve: Check that the valve is in					CI I WO	-112 x 114	makes of Name and Sales
the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or	of the	8 - 1117	IIM = 3	Levis (HIVE	-3.5%	
tubing.) 5.2.4 Solenoid valves: Cycle power to valve to check							
operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)	:						
5.2.5 Fire and shear valves: (a) Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to close completely. (b) Valves must not be wired in open position. (c) Make sure fusible element is in place and correctly positioned. (d) Be sure test ports are sealed with plug after testing is complete and no temporary			ally and				
test fixture or component remains connected to valve.				ort or		- 941114	Kanda degrada — Fr

InnerAll Section	A7 - 30,000 Gallon Ethanol Tank	A8 - 30,000 Gallon Ethanol Tank	A9 - 30,000 Gallon Ethanol Tank	A10 - 30,000 Gallon Ethanol Tank	F1 - 20,000 Gallon Fusel Tank	F2 - 20,000 Galton Fusel Tank	
Item	Yes-No-N/A	Yes-No-N/A	Yes No-N/A	Yes-No-N/A	Yes-Na-N/A	Yes-No-N/A	Comments
5.3 Interstitial leak detection equipment: Check condition of equipment, including; the window is clean and clear in sight leak gauges, the wire connections of electronic gauges for tightness and corrosion, activate the test button, if applicable.	[6] [Tri [0.0]			Transfer of the second	V.C		
5.4 Spill containment boxes on fill pipe: (a) If corrosion damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit. (b) Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary. (c) Drain valves must be operable and closed.				18671		at was	a santa
5.5 Strainer: (a) Check that the strainer is clean and in good condition. (b) Access strainer basket and check cap and gasket seal as well as bolts.					- Efw	-201 C./5D.	
5.6 Filter: (a) Check that the filter is in good condition and is within the manufacturers expected service life. Replace if necessary. (b) Check for leaks and decreased fuel flow.							Assessment of the property of
5.7 Flame arrestors: Follow manufacturer's instructions. Check for corrosion and blockage of air passage.	interior.	William Company	tonic exp	con the		Real Sol	But the second of the second
5.8 Leak detector for submersible pump systems: Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.	1200			lating to	1000	To show	Strategy of the second of the
5.9 Liquid level equipment: (a) Has equipment been tested to ensure proper operation? (b) Does equipment operate as required? (c Follow manufacturer's instructions.	9				SITUAL	m Wika	more and a second second
5.10 Overfill equipment: (a) Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification. (b) Confirm device is suited for above ground use by the manufacturer.	NE S				Mara		
6.0 Insulated Tanks				State of the last			
6.1 Insulation: Check condition of insulation for; missing sections, areas of moisture, mold and damage.		- 11		- I	1001	(12 Fe (1)	The Holland Control of
6.2 Insulation cover or jacket: Check for damage that will allow water intrusion.	43		1300	N. J	2.6.		
7.0 Miscellaneous							In the second second second
7.1 Electrical wiring and boxes: Are they in good condition?					makes	PER STATE	Company and Company and Company
7.2 Labels and tags: Ensure that all labels and tags are intact and readable.		."					DATES DESCRIPTION DE CONTRACTOR

Inspection D	ate:
--------------	------

Inspectors Printed Name:

^{1.} This Annual Inspection Checklist follows Steel Tank institute SP001 checklist guidance.
2. This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be

performed by a certified inspector.

3. Inspect the AST shell and associatd piping, valves, and pumps including inspection of the coating for paint failure.

^{4.} Inspect: Earthen containment structures including examination for holes, washout, and cracking in addition to liner degradation and tank settling. Concrete containment structures and tank foundations/supports including examination of holes, washout, settling, paint failure, in addition to examination for corrosion and leakage. Steel containment strucutres and tank foundations/supports including examination for washout, settling, cracking, and for paint failure, in addition to examination for corrosion and leakage.

^{5.} Inspection of cathodic protection system, if applicable, includes the wire connections for galvanic systems, and visual inspection of the operational components (power switch, meters, and

^{6.} Remove promptly upon discoverty standing water or liquid in the primary tank, secondary containment area, interstice, or spill container. Before discharge to the environment, inspect the

Biguid for oil or sheen and dispose of properly.

7. In order to comply with EPA SPCC rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8©(8)).

^{8.} The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{9.} Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checlists.
10. Note: If change has occurred to the tank system or containment that may affect the SPCC Plan, the should be evaluated against the current plan requirement by a Professional Engineer knowledgable in SPCC development and implementation

Coastal Energy - SPCC Plan
ual Inspection Checklist - Bulk Oil Storage

TOTAL STATE	Annua	al Inspectio		- Bulk Oil S				
	Tank 1 - 30,000 Gallon Asphalt Oil Tank	Tank 2 - 30,000 Gallon Asphalt Oil Tank	Tank 3 - 30,000 Gallon Asphalt Oil Tank	Tank 4 - 30,000 Gallon Asphalt Oil Tank	Tank 5 - 30,000 Gallon Asphalt Oil Tank	Tank 6 - 30,000 Gallon Asphalt Oil Tank	plant project in the second se	
ltem	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Commo	ents
1.0 Tank Containment 1.1 Is the containment structure free from; holes or cracks in the containment wall or floor, washout, liner degradation, corrosion, leakage, paint failure and tank settling?				Alberta Section	5 25 W	in Toleran en ine i un en izazioni illa rivera es	promise for the control of the contr	
2!0 Tank Foundatation and Supports								
2.1 Evidence of tank settlement or foundation washout?			Ľ.			Tak greater		
2.2 Cracking or spalling of concrete pad or ring wall?			77	1 -31-1	alita nagan alitanasian	Ciph Thom	Englishment Action	
2.3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.?				1	10	i i de la companya di sa	B. C. Lovie	
2.4 Water able to drain away from tank?			Ĭij.	7797.4	V5	ALE MAY	5-5 (22/) 	
2.5 Grounding strap secured and in good condition?				15000	resident (p-d = 54	MARK TOWNS	
3.0 Cathodic Protection	ATTENDED	Surgial.		Well Breed				
3.1 Is the CP system functional and includes the wire connections for galvanic systems?							Action (Act)	
3.2(a) Operational components (power switch, meters and alarms) been inspected for working condition?			Ħ.	- Comment				
3.2(b) If applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current system.				11 205	1115 (300 to	disputable	a-Service of respect	
4.0 Tank Shell, Heads and Roof				714 114	PERMIT			
4.1 Evidence of paint failure?				0.00		A STATE OF THE PARTY OF THE PAR		
4.2 Are there any; dents, buckling, bulging, corrosion or cracking in the steel of the tank?				er steet				
4.3 Is there low points or stading water on the roof slope?					405-185-110			
5.0 Tank Equipment			in the last					
5.1 Vents: Verify that components are moving freely and vent passageways are not obstructed for: Emergency vent covers, pressure/vacuum vent poppets and other moving vent components.	104130							
5.2 Valves: Check the condition of all valves for leaks, corrosion and damage.							And the land	
5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation.						500	Edit Life ages.	
5.2.2 Pressure regulator valve: Check for proper operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not visible by looking from above only.)	- 	w_i						
5.2.3 Expansion relief valve: Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or tubing.)	E						THE STATE OF THE S	
5.2.4 Solenoid valves: Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)								

Children Control of the Control of t	Tank 1 - 30,000 Gallon Asphalt Oil Tank	Tank 2 - 30,000 Gallon Asphalt Oll Tank	Tank 3 - 30,000 Gallon Asphalt Oil Tank	Tank 4 - 30,000 Gallon Asphalt Oil Tank	Tank 5 - 30,000 Gallon Asphalt Oll Tank	Tank 6 - 30,000 Gallon Asphalt Oil Tank	
Instance Item week and a man transport	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
5.2.5 Fire and shear valves: (a) Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to close completely. (b) Valves must not be wired in open position. (c) Make sure fusible element is in place and correctly positioned. (d) Be sure test ports are sealed with plug after testing is complete and no temporary test fixture or component remains connected to valve.							
5.3 Interstitial leak detection equipment: Check condition of equipment, including; the window is clean and clear in sight leak gauges, the wire connections of electronic gauges for tightness and corrosion, activate the test button, if applicable.		1		mar está e par para está e para		17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
5.4 Spill containment boxes on fill pipe: (a) If corrosion damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit. (b) Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary. (c) Drain valves must be operable and closed.							
5.5 Strainer: (a) Check that the strainer is clean and in good condition. (b) Access strainer basket and check cap and gasket seal as well as bolts.	Michigan A		TO STATE OF THE ST	Part of the control of	tranto didi Reso mila di del tama	ORAL MODE	man 1900 habitum in despert for the page of Observed and had the beautiful to the page of the con-
5.6 Filter: (a) Check that the filter is in good condition and is within the manufacturers expected service life. Replace if necessary. (b) Check for leaks and decreased fuel flow.	3						
5.7 Flame arrestors: Follow manufacturer's instructions. Check for corrosion and blockage of air passage.							·
5.8 Leak detector for submersible pump systems: Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.	0						
5.9 Liquid level equipment: (a) Has equipment been tested to ensure proper operation? (b) Does equipment operate as required? (c) Follow manufacturer's instructions.	=						
5.10 Overfill equipment: (a) Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification. (b) Confirm device is suited for above ground use by the manufacturer.						;	
6.0 Insulated Tanks	3713330	N. 2 192		-8,4/6			STATE OF THE PROPERTY OF THE P
6.1 Insulation: Check condition of insulation for; missing sections, areas of moisture, mold and damage.							
6.2 Insulation cover or jacket: Check for damage that will allow water intrusion.						V	

Total Action of the Control of the C	Tank 1 - 30,000 Gallon Asphalt Oil Tank	Tank 2 - 30,000 Gallon Asphalt Oil Tank	Tank 3 - 30,000 Gallon Asphalt Oil Tank	Tank 4 - 30,000 Gallon Asphalt Oil Tank	Tank 5 - 30,000 Gallon Asphalt Oil Tank	Tank 6 - 30,000 Gallon Asphalt Oil Tank	
Mincip Item in the American	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
7.0 Miscellaneous	Maria Maria						
7.1 Electrical wiring and boxes: Are they in good		7 1	7		North Article	PATE WINE	ECHAPASSA NESSANDANI
condition?		17			OFFICE	Situatacowa	goden are a office over a
7.2 Labels and tags: Ensure that all labels and tags are	11-1	<u> </u>	- 11	121	madrin the	40.254.000	FY = 775 - 1794 (ST-S) 5-124
intact and readable.				1.17	fer letter	dusted o	lista u mala e ministra

Inspection	Date:
------------	-------

Inspectors	Drintad	Namai

^{1.} This Annual Inspection Checklist follows Steel Tank Institute 5P001 checklist guidance.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Inspect the AST shell and associate piping, valves, and pumps including inspection of the coating for paint failure

^{4.} Inspect: Earthen containment structures including examination for holes, washout, and cracking in addition to liner degradation and tank settling. Concrete containment structures and tank foundations/supports including examination of holes, washout, settling, paint failure, in addition to examination for corrosion and leakage. Steel containment structures and tank foundations/supports including examination for washout, settling, cracking, and for paint failure, in addition to examination for corrosion and leakage.

^{5.} Inspection of cathodic protection system, if applicable, includes the wire connections for galvanic systems, and visual inspection of the operational components (power switch, meters, and alarms) of impressed current systems.

^{6.} Remove promptly upon discoverty standing water or liquid in the primary tank, secondary containment area, interstice, or spill container. Before discharge to the environment, inspect the liquid for oil or sheen and dispose of properly.

^{7.} In order to comply with EPA SPCC rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8@(8)(v).

^{8.} The completed checklists must be maintained for 36 months howver, internal policy dictates that the records will be maintained for a minimum of five years

^{9.} Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checlists

^{10.} Note: If change has occurred to the tank system or containment that may affect the SPCC Plan, the should be evaluated against the current plan requirement by a Professional Engineer knowledgable in SPCC development and implementation.

Coastal Energy - SPCC Plan Annual Inspection Checklist - Bulk Oil Storage Tank 8 -420,000 Gallon Tank 10 -420,000 Gallon Asphalt Oil 420,000 Gallon Asphalt Oil Gallon 210,000 Galon Asphalt Oil 30,000 Gallon Asphalt Oil Tank Asphalt Oil Asphalt Oil Tank 11 -Tank 9 -Comments 1.0 Tank Containment 1.1 Is the containment structure free from; holes or cracks in the containment wall or floor, washout, liner degradation, corrosion, leakage, paint failure and tank settling? 2.0 Tank Foundatation and Supports 2.1 Evidence of tank settlement or foundation washout? 2.2 Cracking or spalling of concrete pad or ring wall? 2.3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.? 2.4 Water able to drain away from tank? 2.5 Grounding strap secured and in good condition? 3.0 Cathodic Protection 3.1 Is the CP system functional and includes the wire connections for galvanic systems? 3.2(a) Operational components (power switch, meters and alarms) been inspected for working condition? 3.2(b) If applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current system. 4.0 Tank Shell, Heads and Roof 4.1 Evidence of paint failure? 4.2 Are there any; dents, buckling, bulging, corrosion or cracking in the steel of the tank? 4.3 Is there low points or stading water on the roof slope? 5.0 Tank Equipment 5.1 Vents: Verify that components are moving freely and vent passageways are not obstructed for: Emergency vent covers, pressure/vacuum vent poppets and other moving vent components. 5.2 Valves: Check the condition of all valves for leaks, corrosion and damage. 5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation. 5.2.2 Pressure regulator valve: Check for proper operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not visible by looking from above only.) 5.2.3 Expansion relief valve: Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or tubing.) 5.2.4 Solenoid valves: Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)

	Market State of State	Tank 7 - 210,000 Galon Asphalt Oil Tank	Tank 8 - 420,000 Gallon Asphalt Oil Tank	Tank 9 - 420,000 Gallon Asphalt Oil Tank	Tank 10 - 420,000 Gallon Asphalt Oll Tank	Tank 11 - 420,000 Gallon Asphalt Oil Tank	Tank 12 - 30,000 Gallon Asphalt Oil Tank	
	ltem	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
	5.2.5 Fire and shear valves: (a) Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to close completely. (b) Valves must not be wired in open position. (c) Make sure fusible element is in place and correctly positioned. (d) Be sure test ports are sealed with plug after testing is complete and no temporary test fixture or component remains connected to valve.							
	5.3 Interstitial leak detection equipment: Check condition of equipment, including; the window is clean and clear in sight leak gauges, the wire connections of electronic gauges for tightness and corrosion, activate the test button, if applicable.	11 .	14				ries sized	Management of the second of th
	5.4 Spill containment boxes on fill pipe: (a) If corrosion damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit. (b) Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary. (c) Drain valves must be operable and closed.		(N. 1873)			NA SEL		
	S.5 Strainer: (a) Check that the strainer is clean and in good condition. (b) Access strainer basket and check cap and gasket seal as well as bolts.					7-0-	st = 6000 on	Control Sal Sal Bendin
mier et	5.6 Filter: (a) Check that the filter is in good condition and is within the manufacturers expected service life. Replace if necessary. (b) Check for leaks and decreased fuel flow.				Bartill,			graduation and the
	5.7 Flame arrestors: Follow manufacturer's instructions. Check for corrosion and blockage of air passage.		1				ole si edu v sessi edu	Egylah ani rikilik ani li Mili madan dan sancia Milinga sakantaka
	5.8 Leak detector for submersible pump systems: Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.							
	5.9 Liquid level equipment: (a) Has equipment been tested to ensure proper operation? (b) Does equipment operate as required? (c) Follow manufacturer's instructions.				9	6 6 7 9	entine in	
	5.10 Overfill equipment: (a) Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification. (b) Confirm device is suited for above ground use by the manufacturer.					Land Control		
	6:0 Insulated Tanks		li de la constante	LO SIALIVE		RENOVATE		
	6.1 Insulation: Check condition of insulation for; missing sections, areas of moisture, mold and damage.					Emilyon	1001 + 1050 1411 - 11	
	6.2 Insulation cover or jacket: Check for damage that will allow water intrusion.							PAGE

THE STATE OF THE S	Tank 7 - 210,000 Galon Asphalt Oil Tank	Tank 8 - 420,000 Gallon Asphalt Oll Tank	Tank 9 - 420,000 Gallon Asphalt Oil Tank	Tank 10 - 420,000 Gallon Asphalt Oil Tank	Tank 11 - 420,000 Gallon Asphalt Oll Tank	Tank 12 - 30,000 Gallon Asphalt Oil Tank	
!tem!tem	Yes-No-N/A	Yes-No-N/A	Yes No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
7.0 Miscellaneous				7 - Service and the service an			
7.1 Electrical wiring and boxes: Are they in good condition?							
7.2 Labels and tags: Ensure that all labels and tags are intact and readable.			A ALEXANDER		The East	10	Maria de la Carta de

Inspect	ion (Dat	e:
---------	-------	-----	----

Inspectors	Printed	Name:

^{1.} This Annual Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.

^{2.} This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.

^{3.} Inspect the AST shell and associate piping, valves, and pumps including inspection of the coating for paint failure.

^{4.} Inspect: Earthen containment structures including examination for holes, washout, and cracking in addition to liner degradation and tank settling. Concrete containment structures and tank foundations/supports including examination of holes, washout, settling, paint failure, in additon to examination for corrosion and leakage. Steel containment structures and tank foundations/supports including examination for washout, settling, cracking, and for paint failure, in additon to examination for corrosion and leakage.

^{5.} Inspection of cathodic protection system, if applicable, includes the wire connections for galvanic systems, and visual inspection of the operational components (power switch, meters, and alarms) of impressed current systems.

^{6.} Remove promptly upon discoverty standing water or liquid in the primary tank, secondary containment area, interstice, or spill container. Before discharge to the environment, inspect the liquid for oil or sheen and dispose of properly.

^{7.} In order to comply with EPA SPCC rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8©(8)(v).

^{8.} The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.

^{9.} Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checlists.

^{10.} Note: If change has occurred to the tank system or containment that may affect the SPCC Plan, the should be evaluated against the current plan requirement by a Professional Engineer knowledgable in SPCC development and implementation.

Coastal Energy - SPCC Plan Annual Inspection Checklist - Bulk Oil Storage 14 -XO Gallon ialt Oil

	Tank 13 30,000 (Asphalt Tank	Tank 14 30,000 (Asphalt Tank	Tank 15 30,000 (Polymer	Tank 16 30,000 (Polymer	Tank 17 30,000 c Asphalt Tank	Tank 18 30,000 c Asphalt Tank	
ltem	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
1.0 Tank Containment							
1.1 Is the containment structure free from; holes or cracks in the containment wall or floor, washout, liner degradation, corrosion, leakage, paint failure and tank settling?					1650	Mesengar A Total (andreas and a control of the control
2.0 Tank Foundatation and Supports	200						
2.1 Evidence of tank settlement or foundation washout?		hilling	E LATE DA				Merchantan engag
2.2 Cracking or spalling of concrete pad or ring wall?			- 1				
2.3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.?	L- W	e e	redirection.	Francis	Pile on age	terminal Top	
2.4 Water able to drain away from tank?	-	eo Jesjahij	Pt Dell	-	1 1000 - 400 - 6	N N H	
2.5 Grounding strap secured and in good condition?	San San Comment			The second	10, 10,		Hart Angeles and the second
3.0 Cathodic Protection							
3.1 Is the CP system functional and includes the wire connections for galvanic systems?	10-1			74		Like in the	The second second second
3 2(a) Operational components (power switch, meters and alarms) been inspected for working condition?	rates or						PATER AND THE PA
3.2(b) If applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current system.	and mark					10-10-02	
4.0 Tank Shell, Heads and Roof	TARLEY.						
4.1 Evidence of paint failure?							
4.2 Are there any; dents, buckling, bulging, corrosion or cracking in the steel of the tank?							
4.3 Is there low points or stading water on the roof slope?							
5.0 Tank Equipment					The state of the s		
5.1 Vents: Verify that components are moving freely		T	· · · · · · · · · · · · · · · · · · ·	T			
and vent passageways are not obstructed for: Emergency vent covers, pressure/vacuum vent poppets and other moving vent components.	~					e	
5.2 Valves: Check the condition of all valves for leaks, corrosion and damage.			4				
5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation.							p 40
5.2.2 Pressure regulator valve: Check for proper operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not visible by looking from above only.)					- V		
5.2.3 Expansion relief valve: Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or tubing.)					5		er *
5.2.4 Solenoid valves: Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)	Ж					8	× .

	Tank 13 - 30,000 Gallon Asphalt Oil Tank	Tank 14 - 30,000 Gallon Asphalt Oil Tank	Tank 15 - 30,000 Gallon Polymer Tank	Tank 16 - 30,000 Gallon Polymer Tank	Tank 17 - 30,000 Gallon Asphalt Oil Tank	Tank 18 - 30,000 Gallon Asphalt Oil Tank	
differential Item more a sound of	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
5.2.S Fire and shear valves: (a) Manually cycle the		CONTRACTOR OF	F 10 10 10 10 10 10 10 10 10 10 10 10 10	19-15-18	CONTRACTOR OF STREET	Y TOUR Y	NAC TANAL MALE TO SE
valve to ensure components are moving freely and			The second second	THE RESERVE	1700	parties of	
that the valve handle or lever has clearance to allow							i in the second
valve to close completely. (b) Valves must not be					32 -= 1	hile periods	THE RESERVE OF THE SECOND
wired in open position. (c) Make sure fusible element							A STATE OF THE STA
is in place and correctly positioned. (d) Be sure test							
ports are sealed with plug after testing is complete				1 3			this Destart A
and no temporary test fixture or component remains connected to valve.							E1=
5.3 Interstitial leak detection equipment: Check		1					
condition of equipment, including; the window is					3 10000		
clean and clear in sight leak gauges, the wire						103	
connections of electronic gauges for tightness and							The start of
corrosion, activate the test button, if applicable.							16 15 15 15 15 15 15 15 15 15 15 15 15 15
5.4 Spill containment boxes on fill pipe: (a) If corrosion	0.00	12 0000	a depth in	to the man	215 DESCRIPTION	1 - 1 - 1 - W - F	and the control of th
damage, or wear has compromised the ability of the	and the	-	A	1,000	PC No. 1941	S. S. F. (192)	the section of the se
unit to perform spill containment functions, replace		mark .		101 y 12	The Committee of the Co	and Artist	Appear of the Control
the unit. (b) Inspect the connections to the AST for	No. of Lot	The same Lake	34				Control of the Contro
tightness, as well as the bolts, nuts, washers for							and the second second
condition and replace if necessary. (c) Drain valves must be operable and closed.	appeal and the first	Page 19			100	400 - 1 to	
5.5 Strainer: (a) Check that the strainer is clean and in				-		and the same	
good condition. (b) Access strainer basket and check		100000000000000000000000000000000000000		office State	mark was a series		Considerate to the star of
cap and gasket seal as well as bolts.	PROMING A SIG	ALCOHOLD IN	CO 107	Wite The Party		saves " limber	empresent and the state of
5.6 Filter: (a) Check that the filter is in good condition					5	71 (1) (2) (3)	Contractive and a respective state.
and is within the manufacturers expected service life		1					
Replace if necessary. (b) Check for leaks and							FC40
decreased fuel flow.						- TO	
5.7 Flame arrestors: Follow manufacturer's							
instructions. Check for corrosion and blockage of air	1						
passage.							
5.8 Leak detector for submersible pump systems: Test							
according to manufacturer's instructions and authority							
having jurisdiction (AHJ). Verify leak detectors are				8		1	
suited and properly installed for aboveground use.		1					
5.9 Liquid level equipment: (a) Has equipment been							
tested to ensure proper operation? (b) Does		1 5		1			
equipment operate as required? (c) Follow		1					
manufacturer's instructions							
5.10 Overfill equipment: (a) Follow manufacturer's							
instructions and regulatory requirements for							N 52
inspection and functionality verification. (b) Confirm							
device is suited for above ground use by the							
manufacturer.				1			the state of the s
6.0 Insulated Tanks	enwire - E	1	-	T	Ť-	T	T
6.1 Insulation: Check condition of insulation for;							
missing sections, areas of moisture, mold and damage.							
6.2 Insulation cover or jacket: Check for damage that		2		1			
will allow water intrusion.		1		1			

	Tank 13 - 30,000 Gallon Asphalt Oil Tank	Tank 14 - 30,000 Gallon Asphalt Oil Tank	Tank 15 - 30,000 Gallon Polymer Tank	Tank 16 - 30,000 Gallon Polymer Tank	Tank 17 - 30,000 Gallon Asphalt Oil Tank	Tank 18 - 30,000 Gallon Asphalt Oil Tank	
Item to Account	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
7.0 Miscellaneous			BUENE				
7.1 Electrical wiring and boxes: Are they in good	1.5				- Alkiel	A Section Action	第7章に対して10年に10年に
condition?		1	1			year to sever firm	All a restaurate to several little
7.2 Labels and tags: Ensure that all labels and tags		N.			15.00	Dam shipping	DENSEMBLE DESCRIPTIONS
are intact and readable.						this does not be	Complete participate in the contract of

Inspection Date:			
	 -		
Inspectors Printed Name:		Inspectors Signature:	

- 1. This Annual Inspection Checklist follows Steel Tank Institute SP001 checklist guidance
- 2. This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.
- 3. Inspect the AST shell and associate piping, valves, and pumps including inspection of the coating for paint failure.
- 4. Inspect: Earthen containment structures including examination for holes, washout, and cracking in addition to liner degradation and tank settling. Concrete containment structures and tank foundations/supports including examination of holes, washout, settling, paint failure, in additon to examination for corrosion and leakage. Steel containment structures and tank foundations/supports including examination for washout, settling, cracking, and for paint failure, in addition to examination for corrosion and leakage.
- 5. Inspection of cathodic protection system, if applicable, includes the wire connections for galvanic systems, and visual inspection of the operational components (power switch, meters, and alarms) of impressed current systems.
- 6. Remove promptly upon discoverty standing water or liquid in the primary tank, secondary containment area, interstice, or spill container. Before discharge to the environment, inspect the liquid for oil or sheen and dispose of properly.

 7. In order to comply with EPA SPCC rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8©(8)(v).
- 8. The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five year:
- 9. Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checlists
- 10. Note: If change has occurred to the tank system or containment that may affect the SPCC Plan, the should be evaluated against the current plan requirement by a Professional Engineer knowledgable in SPCC development and implementation.

Coastal Energy - SPCC Plan Annual Inspection Checklist - Bulk Oil Storage Tank 22 -30,000 Galfon Asphalt Oil Tank 30,000 Gallon Asphalt Oil Tank Tank 19 -30,000 Gallon Asphalt Oil Tank 30,000 Gallon Asphalt Oil Tank 30,000 Gallon Asphalt Oil 30,000 Gallon Asphalt Oil Tank 20 -Tank 24 -Tank 21 -Tank 23 -Comments Item Yes-No-N/A Yes-No-N/A Yes-No-N/A Yes-No-N/A 1.0 Tank Containment 1.1 is the containment structure free from; holes or cracks in the containment wall or floor, washout, lines degradation, corrosion, leakage, paint failure and tank settling? 2.0 Tank Foundatation and Supports 2.1 Evidence of tank settlement or foundation washout? 2.2 Cracking or spalling of concrete pad or ring wall? 2 3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.? 2.4 Water able to drain away from tank? 2.5 Grounding strap secured and in good condition? 3.0 Cathodic Protection 3.1 Is the CP system functional and includes the wire connections for galvanic systems? 3.2(a) Operational components (power switch, meters and alarms) been inspected for working condition? 3.2(b) If applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current 4.0 Tank Shell, Heads and Roof 4.1 Evidence of paint failure? 4.2 Are there any; dents, buckling, bulging, corrosion o cracking in the steel of the tank? 4.3 Is there low points or stading water on the roof slope? 5.0 Tank Equipment 5.1 Vents: Verify that components are moving freely and vent passageways are not obstructed for: Emergency vent covers, pressure/vacuum vent poppets and other moving vent components. 5.2 Valves: Check the condition of all valves for leaks, corrosion and damage. 5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation. 5.2.2 Pressure regulator valve: Check for proper operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not visible by looking from above only.) 5.2.3 Expansion relief valve: Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or tubing.) 5.2.4 Solenoid valves: Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)

		Tank 19 - 30,000 Gallon Asphalt Oil Tank	Tank 20 - 30,000 Gallon Asphak Oil Tank	Tank 21 - 30,000 Gallon Asphalt Oil Tank	Tank 22 - 30,000 Gallon Asphalt Oil Tank	Tank 23 - 30,000 Gallon Asphałt Oil Tank	Tank 24 - 30,000 Gallon Asphalt Oil Tank	*
	ltem	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
	5.2.5 Fire and shear valves: (a) Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to close completely. (b) Valves must not be wired in open position. (c) Make sure fusible element is in place and correctly positioned. (d) Be sure test ports are sealed with plug after testing is complete and no temporary test fixture or component remains connected to valve.			A Maria				
2	5.3 Interstitial leak detection equipment: Check condition of equipment, including; the window is clean and clear in sight leak gauges, the wire connections of electronic gauges for tightness and corrosion, activate the test button, if applicable.			- 4				
	5.4 Spill containment boxes on fill pipe: (a) If corrosion damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit. (b) Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary. (c) Drain valves must be operable and closed.	u sarah Li sarah	1 35 0	ME				
	5.5 Strainer: (a) Check that the strainer is clean and in good condition. (b) Access strainer basket and check cap and gasket seal as well as bolts.			52	77		Treatment of the same of the s	
	5.6 Filter: (a) Check that the filter is in good condition and is within the manufacturers expected service life. Replace if necessary. (b) Check for leaks and decreased fuel flow.	er getal						
	5.7 Flame arrestors: Follow manufacturer's instructions. Check for corrosion and blockage of air passage.	li li						
Mr	5.8 Leak detector for submersible pump systems: Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.			Topic sa	1 1 1 m	Maga-gl		The state of the s
	5.9 Liquid level equipment: (a) Has equipment been tested to ensure proper operation? (b) Does equipment operate as required? (c) Follow manufacturer's instructions.				117	1 - 01248		THE STATE OF THE S
	5.10 Overfill equipment: (a) Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification. (b) Confirm device is suited for above ground use by the manufacturer.						- Danie	-246
	6.0 Insulated Tanks						it any for	1000 100 100 100 100 100 100 100 100 10
	6.1 Insulation: Check condition of insulation for; missing sections, areas of moisture, mold and damage.	,					Middle .	DELX S. A. DECE
	6.2 Insulation cover or jacket: Check for damage that will allow water intrusion.						PRESCONDE	

ogra-d	Tank 19 - 30,000 Gallon Asphalt Oil Tank	Tank 20 - 30,000 Gallon Asphalt Oil Tank	Tank 21 - 30,000 Gallon Asphalt Oil Tank	Tank 22 - 30,000 Gallon Asphalt Oil Tank	Tank 23 - 30,000 Gallon Asphalt Oil Tank	Tank 24 - 30,000 Gallon Asphalt Oil Tank	
Item	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
7.0 Miscellaneous	LIBERT STREET		Name and A				
7.1 Electrical wiring and boxes: Are they in good condition?	155	而并高上		SH SE			
7.2 Labels and tags: Ensure that all labels and tags are intact and readable.	2.1/4			BELLW			E. Santon Herrick

Inspection Date:

Inspectors Printed Name:

- 1 This Annual Inspection Checklist follows Steel Tank Institute SP001 checklist guidance
- 2 This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.
- 3. Inspect the AST shell and associate piping, valves, and pumps including inspection of the coating for paint failure.
- 4. Inspect: Earther containment structures including examination for holes, washout, and cracking in addition to liner degradation and tank settling. Concrete containment structures and tank foundations/supports including examination of holes, washout, settling, paint failure, in addition to examination for corrosion and leakage. Steel containment structures and tank foundations/supports including examination for washout, settling, cracking, and for paint failure, in addition to examination for corrosion and leakage
- 5 Inspection of cathodic protection system, if applicable, includes the wire connections for galvanic systems, and visual inspection of the operational components (power switch, meters, and alarms) of impressed current systems.
- 6. Remove promptly upon discoverty standing water or liquid in the primary tank, secondary containment area, interstice, or spill container. Before discharge to the environment, inspect the liquid for oil or sheen and dispose of properly.
- 7. In order to comply with EPA SPCC rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8©(8)(v).

 8. The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years.
- 9. Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checklists.

 10. Note: If change has occurred to the tank system or containment that may affect the SPCC Plan, the should be evaluated against the current plan requirement by a Professional Engineer knowledgable in SPCC. development and implementation

Coastal Energy - SPCC Plan Annual Inspection Checklist - Bulk Oil Storage Used Oil - 1,100 Gallon Used Oil 17,500 Gallon Diesel Tank Diesel Tank 1 -12,000 Gallon Diesel Tank 2 6,000 Gallon Diesel Tank **Diesel Tank** Tank B1 -Item Yes-No-N/A Yes-No-N/A Yes-No-N/A Yes-No-N/A Yes-No-N/A Comments 1.0 Tank Containment 1.1 Is the containment structure free from; holes or cracks in the containment wall or floor, washout, liner degradation, corrosion, leakage, paint failure and tank settling? 2.0 Tank Foundatation and Supports 2.1 Evidence of tank settlement or foundation washout? 2.2 Cracking or spalling of concrete pad or ring wall? 2.3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.? 2.4 Water able to drain away from tank? 2.5 Grounding strap secured and in good condition? 3.0 Cathodic Protection 3.1 Is the CP system functional and includes the wire connections for galvanic systems? 3.2(a) Operational components (power switch, meters and alarms) been inspected for working condition? 3.2(b) If applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current system. 4.0 Tank Shell, Heads and Roof 4.1 Evidence of paint failure? 4.2 Are there any; dents, buckling, bulging, corrosion or cracking in the steel of the tank? 4.3 Is there low points or stading water on the roof slope? 5.0 Tank Equipment 5.1 Vents: Verify that components are moving freely and vent passageways are not obstructed for: Emergency vent covers, pressure/vacuum vent poppets and other moving vent components. 5.2 Valves: Check the condition of all valves for leaks, corrosion and damage. 5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation. 5.2.2 Pressure regulator valve: Check for proper operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not visible by looking from above only.) 5.2.3 Expansion relief valve: Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or tubing.) 5.2.4 Solenoid valves: Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)

	Tank B1 - 12,000 Gallon Diesel Tank	Diesel Tank 1 - 6,000 Gallon Diesel Tank	Diesel Tank 2 - 17,500 Gallon Diesel Tank	Used Oil - 1,100 Gallon Used Oil Tank			
Item wanted 1	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
5.2.5 Fire and shear valves: (a) Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to close completely. (b) Valves must not be wired in open position. (c) Make sure fusible element is in place and correctly positioned. (d) Be sure test ports are sealed with plug after testing is complete and no temporary test fixture or component remains connected to valve.						112 m	
5.3 Interstitial leak detection equipment: Check condition of equipment, including; the window is clean and clear in sight leak gauges, the wire connections of electronic gauges for tightness and corrosion, activate the test button, if applicable.		-11	enders of	- X		Station of	
5.4 Spill containment boxes on fill pipe: (a) If corrosion damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit. (b) Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary. (c) Drain valves must be operable and closed.							The second first of the second
5.5 Strainer: (a) Check that the strainer is clean and in good condition. (b) Access strainer basket and check cap and gasket seal as well as bolts.							mix displayed (2000) search for the control of the
5.6 Filter: (a) Check that the filter is in good condition and is within the manufacturers expected service life. Replace if necessary. (b) Check for leaks and decreased fuel flow.							
5.7 Flame arrestors: Follow manufacturer's instructions. Check for corrosion and blockage of air passage.							
5.8 Leak detector for submersible pump systems: Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.							
5.9 Liquid level equipment: (a) Has equipment been tested to ensure proper operation? (b) Does equipment operate as required? (c) Follow manufacturer's instructions.							
5.10 Overfill equipment: (a) Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification. (b) Confirm device is suited for above ground use by the manufacturer.							
6.0 Insulated Tanks				NAME OF THE OWN			
6.1 Insulation: Check condition of insulation for; missing sections, areas of moisture, mold and damage.				.00			
6.2 Insulation cover or jacket: Check for damage that will allow water intrusion.							

	Tank B1 - 12,000 Gallon Diesel Tank	Diesel Tank 1 - 6,000 Gallon Diesel Tank	Diesel Tank 2 - 17,500 Gallon Diesel Tank	Used Oil - 1,100 Gallon Used Oil Tank		li a	
4589 600 Item sever Language In	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
7.0 Miscellaneous							
7.1 Electrical wiring and boxes: Are they in good condition?				- 1	A Sice	Complete States	BOOKSTONE SECTION OF THE SECTION OF
7.2 Labels and tags: Ensure that all labels and tags are intact and readable.				138	THE LIGHT		Books and the state of the stat

Inspectors Printed Name:	Inspectors Signature:	
Inspection Date:		

- 1. This Annual Inspection Checklist follows Steel Tank Institute SP001 checklist guidance.
- 2. This AST inspection is intended for monitoring the external tank condition and containment structure. The inspection shall be performed by the owners inspector and does not have to be performed by a certified inspector.
- 3. Inspect the AST shell and associatd piping, valves, and pumps including inspection of the coating for paint failure.
- 4. Inspect: Earthen containment structures including examination for holes, washout, and cracking in addition to liner degradation and tank settling. Concrete containment structures and tank foundations/supports including examination of holes, washout, settling, paint failure, in addition to examination for corrosion and leakage. Steel containment structures and tank foundations/supports including examination for washout, settling, cracking, and for paint failure, in addition to examination for corrosion and leakage.
- 5. Inspection of cathodic protection system, if applicable, includes the wire connections for galvanic systems, and visual inspection of the operational components (power switch, meters, and alarms) of impressed current systems.
- 6. Remove promptly upon discoverty standing water or liquid in the primary tank, secondary containment area, interstice, or spill container. Before discharge to the environment, inspect the liquid for oil or sheen and dispose of properly.
- 7. In order to comply with EPA SPCC rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8®(8)(v).
- 8. The completed checklists must be maintained for 36 months hower, internal policy dictates that the records will be maintained for a minimum of five years
- 9. Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checlists
- 10. Note: If change has occurred to the tank system or containment that may affect the SPCC Plan, the should be evaluated against the current plan requirement by a Professional Engineer knowledgable in SPCC development and implementation.

Nember (1916) 3 - Library was a strong factor of	Emergency Backup Generator - 400 Gallon	Used Oil Heater - 250 Gallon	and the second	Aragraph A	reservatività	resolution (us Senting transport specific deal
ltem	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
1.0 Tank Containment 1.1 is the containment structure free from; holes or				1	CONTRACTOR CONTRACT	S 700 (90)	parent a company approximation
cracks in the containment wall or floor, washout, liner degradation, corrosion, leakage, paint failure and tank settling?					Taliceyon, rigi Juano - Ture (Niberio XII)	Lewista Built Valencia de Escribbility	pskin i na Ren (1965) Pskin i na stenjištvi i na postavija potestili i nat
2.0 Tank Foundatation and Supports							
2.1 Evidence of tank settlement or foundation							
washout?							
2.2 Cracking or spalling of concrete pad or ring wall?							BADONER SHE THOUSE WITH THEY
2.3 Tank supports in satisfactory condition and free from corrosion, paint failure, etc.?					THE R. LEWIS CO.	COLUMN TO SERVICE	ming in
			77				ACCUSED TO SERVICE AND ADDRESS OF THE PARTY
2.4 Water able to drain away from tank?					market by	gibing filter.	Section of the second
2.5 Grounding strap secured and in good condition?					TE COMMENT HES DATES OF THE COMMENT	to the en	Marini de la compania del compania del compania de la compania del compania del compania de la compania del
3.0 Cathodic Protection						The Park	
3.1 Is the CP system functional and includes the wire	1.50		V H	- 3	00 612	for it now	entral al-Alim has recently
connections for galvanic systems?		i id			11 7Q. HK		Charles and the second
3.2(a) Operational components (power switch, meters and alarms) been inspected for working condition?			*		a ve mis	Section 1	and the state of the state of
3.2(b) if applicable, record the hour meter, ampmeter and voltmeter readings of the impressed current system.					Pardinate	0007	Application (2) to the second of the second
4.0 Tank Shell, Heads and Roof	127.192		RAUS IN			RESERVED NO	
4.1 Evidence of paint failure?				0 14	PROPERTY FOR		OUTDING THE SAME AND ADDRESS OF THE SAME AND ADDRESS O
4.2 Are there any; dents, buckling, bulging, corrosion or cracking in the steel of the tank?					151-276	introbac Instruppi	enalista esta en 6.0 (14) (15) (15) en en esta en 6.0 (14) (15) (15) (15) (15) (15) (15) (15) (15
4.3 Is there low points or stading water on the roof slope?					SHOOLINE OF THE	Paul Mail	Same transmission of
5.0 Tank Equipment							in term it operately workers
5.1 Vents: Verify that components are moving freely and vent passageways are not obstructed for: Emergency vent covers, pressure/vacuum vent poppets and other moving vent components.					2y/10/29		All and the state of the state
5.2 Valves: Check the condition of all valves for leaks, corrosion and damage.					5/1944	EGT TANKE	Accompany and and
5.2.1 Anti-siphon check and gate valves: Cycle the valve open and closed and check for proper operation.						tintoilio estilio	M. Secretaria de Verra de La Companya de La Company
5.2.2 Pressure regulator valve: Check for proper operation. (Note that there may be small, 1/4 inch drain plugs in the bottom of the valve that are not			. marke				
visible by looking from above only.)	September 1		The state of	N.B.		123.3	
5.2.3 Expansion relief valve: Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or					CONTRACTOR OF THE		Section of the section of
tubing.)		-	1		7 3 3	21 0000	
5.2.4 Solenoid valves: Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)		-					

	400	ater	10				
to manual.	Emergency Backup Generator - Gallon	Used Oil Heater - 250 Gallon		may X			
Item	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Yes-No-N/A	Comments
5.2.5 Fire and shear valves: (a) Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to close completely. (b) Valves must not be wired in open position. (c) Make sure fusible element is in place and correctly positioned. (d) Be sure test ports are sealed with plug after testing is complete and no temporary test fixture or component remains connected to valve.						X17	the control of the co
5.3 Interstitial leak detection equipment: Check condition of equipment, including; the window is clean and clear in sight leak gauges, the wire connections of electronic gauges for tightness and corrosion, activate the test button, if applicable.	= 1,				20 (2 M) (2 M)	4110L	To the contract of the contrac
5.4 Spill containment boxes on fill pipe: (a) If corrosion damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit. (b) Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary. (c) Drain valves must be operable and closed.	77						The state of the s
5.5 Strainer: (a) Check that the strainer is clean and in good condition. (b) Access strainer basket and check cap and gasket seal as well as bolts.					-59 -46	1461 9010 10	The particular of the second o
5.6 Filter: (a) Check that the filter is in good condition and is within the manufacturers expected service life. Replace if necessary. (b) Check for leaks and decreased fuel flow.	5.745		BEE E		Market Se	34 4	
5.7 Flame arrestors: Follow manufacturer's instructions. Check for corrosion and blockage of air passage.					4	NY YOUR	properties productions of the second
5.8 Leak detector for submersible pump systems: Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.			E 42		Maria de la composition della		A CONTRACTOR OF THE CONTRACTOR
5.9 Liquid level equipment: (a) Has equipment been tested to ensure proper operation? (b) Does equipment operate as required? (c) Follow manufacturer's instructions.					- Min	,	End for a government of a
5.10 Overfill equipment: (a) Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification. (b) Confirm device is suited for above ground use by the manufacturer.				:	entare estare	on the particular of the parti	Secretary the many that is a secretary that is a secretary that is a secretary to the secretary that is a secretary th
6.0 Insulated Tanks						42.7	o membe salt en exalta are in a
6.1 Insulation: Check condition of insulation for; missing sections, areas of moisture, mold and damage.				21	Application of	Ser leit	AND THE STREET OF THE STREET
6.2 Insulation cover or jacket: Check for damage that will allow water intrusion.			- 3		Association		Proceedings of the Process of the Pr